

Chief Ship Surveyor

11. 9. 13

Received from Chief Ship Surveyor

NAME

Sll ss " Silvio "

Rpt.

Sun

No. 7783

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Survey

First Entry

It is submitted the Hull Surveyors be informed that this vessel has proceeded to their port to have her Machinery fitted on board, and to complete the survey on the hull the following requires to be done:-

Tunnel to be tested complete

Tunnel W. T. door to be examined and tested

Downton pump to be tested

Bridge deck, casings, etc. in way of machinery space to be riveted up, and deck tested in way of same


Tonnages to be completed

Pillaring in machinery space to complete

They should be requested to give the case the necessary attention, and on completion of the work to forward a report on Form 8 with a view to the classification of the vessel.

It is further submitted this report be returned to the Dundee Surveyors, who should be requested to fill in the spacing of the rivets and seams and butts of the shell plating.

Hull & Dundee 12/9/13



12. 9. 13

Lloyd's Register
Foundation
W262-0068

Spacing

46

46

Poop Deck Stringer Plate, breadth & thickness

52-24

Dock

Decks with
Tiers ofnd of U
Beam, AInches
Spacing
Ship.

46

204

444

474

Inches
Ship. in S