

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Twin Screw M.S. "TARIFA" Rpt. Dnz. No. 12

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Longitudinal ~~Transverse~~ No. 19150 Depth "d"
Framing: Table No. Description Bulb angle frames as approved

2nd Longitudinal No. 49620
Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{11.27}{\dots}$

~~Deck~~ Sheerstrake As approved (+ Owners' increase)

On account of damage through fire whilst building repairs have been effected to shell plating, framing, bulkheads etc.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~*100A1~~ "with freeboard," as recommended. The Summer freeboard of See from centre of disc Verification Form to top of ~~statutory~~ deck line at deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

1 Dk. & Shl. Dk. 3rd Dk. except in after holds
"Bulbs of deck plating electrically welded"
Cell. DB 349' 1512t, MT 30' 143lt, Tanks in way of tunnels 390t, FPT 82t, APT 273t
FK, 'One Intermediate BH dispensed with, Coll. BH to Shl. Dk. 6 BH to 2nd Dk.'
pt. Cem., Lloyd's A & CP.
P 42', F 26' Rudder electrically welded. 1/2

© 2019 Lloyd's Register Foundation
W264-0267
P.T.O.

17/4/38
RE-TARIFA
[Signature]

20

Faint, illegible text, likely bleed-through from the reverse side of the page.



© 2019
Lloyd's Register
Foundation

L.R.

"TARIFA"

-2-

It is concluded the diameter and spacing of the rivets in the butts of the strake below the sheerstrake are as required by the Rules and that the arrangements of the pillaring are as approved throughout.

dn 27/12

Yes! See better



© 2019

Lloyd's Register

Foundation 0267

242 W269