

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 5th Dec. 1942 When handed in at Local Office 7. 11. 42 Port of GLASGOW.

No. in Survey held at GLASGOW.

Date, First Survey 1st Dec. Last Survey 2nd Dec. 1942

84503 on the Wood, Iron or Steel T.S.S. "VESTFOLD"

TONNAGE:-

GROSS 14547

UNDER DECK 9942

NET 8277

Built at HAVERTON HILL-ON-TEES By whom FURNESS S.B. CO. LD

When 1931

Owners VESTFOLD CORPORATION.

Owners' Address

Managers

Port belonging to PANAMA.

Surveyed Afloat or in Dry Dock? DRY DOCK Name of Dock ELDERSLIE No. 2. Destined Voyage

Cell/Dor/Dba feet; uE&B feet; f feet
total capacity tons. F.P.T. tons; A.P.T. tons; M.T. tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 42983 Port N.Y.K.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

DAMAGE & DOCKING.

DAMAGE:- stated to have been sustained to starboard quarter by drifting onto the stem and chain moorings of the T.S. Strathallan during stormy weather on the 9th Oct. 1942 in the Holy Loch. (Please see Fremoch Report No. 22044)

NOW DONE:- Vessel placed in drydock, under water plating and rudder examined, found no signs of vessel having sustained any damage.

TO COMPLETE DAMAGE:- Permanent repairs require to be effected to Boat Deck plating, stanchions, etc., 1 poop sheerstrake plate, and plating of poop deckhouse accommodation on starboard quarter, at first convenient opportunity. This has now been examined and found satisfactory for the present.

DOCKING:- Vessel placed in drydock, bottom and rudder cleaned, examined, found satisfactory P.T.O.

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	good	Bulkheads	good in spaces span ^d	Engine Room Skylights	good	Copper, or I.M.	
Caulking of Decks	good	Ceiling	good in spaces span ^d	Coal Bunkers, Openings, Covers, &c.	good	(State if on Fair)	
Stanchions	good	Cement or Asphalt	not span ^d	Oil Bunkers		When Stated, Month	Year
Rivets & Fastenings	good in spaces span ^d	Rudder	good	Scuppers	not span ^d	Boats	not span ^d
Outside Plating	good	Steering gear and its connections	good	Cargo Hatchways	good	Masts, &c.	good
" " in way of sidelights	not span ^d	Windlass	good	Hatches	good	Condition, how ascertained	from deck
Frames	good in spaces span ^d	Have pumps been examined and found efficient?	not span ^d	Planking		(State if wedges removed)	no
Transverse Frames		Have Sluice Valves been examined and found efficient?	not span ^d	Caulking		Equipment letter	jt
Longitudinals	good in spaces span ^d	Have Watertight Doors been examined and found efficient?	not span ^d	Treenails		Anchors, No. of	3-1
Booms	not span ^d	Have Ventilators and their Coamings been examined and found efficient?	yes	Breasthooks & Stemson		Cables (State if now ranged)	no
Belsons	not span ^d	Air and Sounding Pipes	not span ^d	Transoms, Pointers, & Crutches		" length, COMPLETE (on board)	mean diam. —
Ringers	good in spaces span ^d	Doubling Plates under Sounding Pipes	not span ^d	Timbers of Frame at openings		" Rule length	— size —
Inner Bottom Plating	good in spaces span ^d			Stringers, Clamps & Shelves		Chain Locker	not span ^d
Have the Tanks been examined internally?	no			Sanding	(state if examined.)	Hawsers & Warps	sufficient
Have the Tanks been tested?	no					Standing and Running Rigging	good

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."


This vessel, so far as now seen, is in an efficient condition and eligible in my opinion to remain as at present classed in the Register Book with a fresh record of survey 12.42 subject to permanent repairs to boat deck plating, stanchions, etc., 1 poop sheerstrake plate, and plating of poop deckhouse accommodation on starboard quarter, at first convenient opportunity.

Survey Fee (per Section 20)	£	Fees applied for,	
Special Damage or Repair Fee (if any) (per Sec. 20)	£	19	
Travelling Expenses (if chargeable)	£	Received by me,	
and Surveyor's Fee (if any)	£	19	

Committee's Minute GLASGOW 8 DEC 1942

Character Assigned 100A 12.42 } subject
S.H. 42 } with pda:
Car. oil fuel &c: sea for oil fuel &c

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation

W270-0003

DOCKING CONTI :- and recoated.

Deck, casing, hatch, coamings, ventilators etc., examined and found satisfactory.
Forward Hold and Tween Decks also No. 2 Large Oil Tank generally examined and
found satisfactory.
Freeboard rough checked.

NOW DONE :- A few minor deck repairs effected.

STEERING GEAR:- This vessel is not fitted with rod and chain steering gear.
Auxiliary steering gear generally examined and found satisfactory.

1 DOCKING

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.			WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and by Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.			
	1st Bower															
	2nd "															
	3rd "															
	Collective Weight.															
	Steam															
	Kedge.															

If Patent state name of Patentee.

U. S. PATENT OFFICE.

MECHANICAL TEST.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

Iron Stream Chain }
or Steel Wire...