

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office, 17 SEP 1942)

Date of writing Report 20. 8. 1942 When handed in at Local Office 22/8/42 Port of NEWCASTLE-ON-TYNE

No. in Reg. Book 4503 Survey held at Hutton-on-Tyne Date, First Survey 24. 7. 42 Last Survey 15. 8. 1942 (No. of Visits 5)

on the Machinery of the Wood, Iron or Steel Tu. Sc. S. Vestfold.

Tonnage Gross 14547 Net 8277 Vessel built at Hunter Hill - A. J. J. By whom Furness & Co. Ld. When 1931 7

Nominal Horse Power 997 Engines made at Hartlepool By whom Richardson, Wigham & Co. Ld. When 1931

No. of Main Boilers 558 Boilers, when made (Main) 1931 (Donkey) ✓ Owners Vestfold Exporters. Owners' Address (if not already recorded in Appendix to Register Book) Port Panama Voyage ✓

No. of Donkey Boilers 1 Managers ✓ Steam Pressure in Main Boilers 265 lb. If Surveyed Afloat or in Dry Dock Afloat. (State name of Dock.)

In Donkey Boilers ✓ Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. Port B.S.

Particulars of Examination and Repairs (if any) B.S.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? ✓

If this was not done, state for what reasons? ✓

and what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler. 28/7/42 Present condition of funnel(s) Good

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 265 lb.

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes , and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ , and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? Yes , and of the Donkey Boilers? ✓

Has screw shaft now been drawn and examined? ✓ Is it fitted with continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? ✓ If so, state reasons ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft ✓ State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft ✓

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted Yes

So, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Was the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

How done: - The main boilers examined throughout & mountings & their safety valve & Sph. safety valves adjusted under steam as above.

Repairs: - Main & Donkey: - F.P. & F.S. Boilers water gauge, water and cock checks renewed. Stopped tubes renewed.

By order of the Authorities the factory has been partly stripped & pumps & a large number of steam & exhaust pipes have been removed & placed ashore. The factory steam master-valve-check on boiler tops found fractured around joints & removed & steam line blanked off.

It is stated that the entire factory is to be removed ashore on the vessel's return for the present voyage.

General Observations, Opinion, and Recommendation: - The Machinery of this vessel, as far as (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, E.S. 9.11, B.&M.S. 9.11, & L.M.C. 9.11, or L.M.C. 140 lb., F.D., &c.)

How run, is eligible in my opinion to remain as classed with fresh records of 15. 8. 42

R.L. Form attached Rpt. 8.

Survey Fee (per Section 29) £ 6 : 0 : 0 Fees applied for 16 SEP 1942

Special Damage or Repair Fee (if any) (per Section 29) £ : : Received by me, 19

Travelling expenses (if chargeable) £ : : Geo. J. H. S. S. S. Engineer Surveyor to Lloyd's Register of Shipping.

License Base Committee's Minute FRI 9 OCT 1942

Assigned R.H.S. Subject



FOOD-OFTN

As held  
The self factory has been partly  
dismantled.

As 842

Subject to the  
PRESS BOILERS  
not being used

As 842  
As 842

*[Faint vertical handwriting, likely bleed-through from the reverse side of the page]*

*[Faint vertical handwriting on the right side of the page, including some illegible words and numbers]*