

10396

Deck at side to top of keel

Residence 20 Broadway, N.Y.C.
VICTORIA B.C.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *Steel S.S. "VICTOLITE"*Rpt. *NK*No. *20539*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

It is Submitted the Surveyors be requested to forward the usual particulars of the Constitutional framing etc as Report 1 as this does not appear to have been received with the first entry report*

*LD**10/8/21**M**AD*
9.8.21

© 2021

Lloyd's Register
Foundation

W28-0014

state if flanged (top & bottom)

*40**✓**40**24**to report*

The Plates, fore and aft, outside hatchways

Deck * *Lower* Steel for *hull*

Ingr

50