

BorDBa feet; uE&B feet; f feet | Particulars of Class  
Described by  
Precisely as in H

Memo. respecting incomplete survey on  
the S.S. Emmy.

London 3rd June 1942.

- (1) The leaky rivets in bottom plating were repaired  
i.e. Shell plate DY, port side. London Report No 110408.
- (2) The undersigned had no knowledge of the  
life boat davit requiring to be faired, and no mention  
was made of it by the Owners.
- (3) The bolt in shell plating (S.S.) in way of chain  
locker was removed & plate part doubled. i.e. Shell  
plate H.1. London Report No 110408.

It is regretted that these items were not made clear in  
the London Report 110408.

J. Nicholas.  
Surveyor.

FOR { MR. HILL.  
MR. NETTLETON.

1m, 7, 39.

recommended.



Lloyd's Register  
Foundation

W28-0154