

17 APR 1939

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME "THOMAS BARTLETT"

Rpt. Mil.

No. 5460

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

The class is subject to a garboard plate in way of midship tank E.W. repair 12.36 being examined at the next dry docking.

The Milford Haven Surveyor now reports this trawler placed in dry dock bottom coated and on account of damage through striking dock wall three shell plates renewed, repairs to shell plating, framing, stem etc. carried out. A bower anchor has been supplied it being stated that another anchor is being repaired.

The garboard plate as above has been examined and the Surveyors recommend the condition of class relative thereto be now deleted.

It is submitted the vessel appears worthy to remain as classed with record of survey 3.39, without special condition.

100A1)
Steam Trawler) Without etc.
3.39 Mil)

all. *YH* 13.4.39

W



© 2020

Lloyd's Register Foundation

W282-0064