

Less Engine Room 2230.26
Less Navigation Spaces 135.95

Upper Deck at side 14.3

Port belonging to *Hollis*
W367-0001

1m, 12, 15.

RETAIN

F.E.

Received by Chief Ship Surveyor _____ Received from Chief Ship Surveyor _____

VESSEL'S NAME *Steel S.S. CANADIAN CRUISER* Rpt. *Afx* No. *1372*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *86* Depth "d" *17.25*

Framing: Table No. *3* Description *Bull-angles as approved*

Longitudinal No. *36980*

Shelter Proportions Length = *11.3*
Depth =

Deck Sheerstrake *as approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100-A-1 (Steel) "Shelter Deck"* with freeboard, as recommended. The Summer freeboard of *9-2 1/2* from centre of disc to top of statutory deck line at *Shelter* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

2 Dhs (Steel) & Shelter Dh. (Steel)

Cell D/B 360' 1159t, D/Ta 24' 62st, FPT 132t APT 128t,

FK, 2 BH to Shelter Dh 5 BH to upper Dh, pt Ceun, Av. CP, P46 F45 on Shelter Dh

a webframe is fitted in the deep tank. It is concluded the Collision bulkhead extends to the shelter deck. Horizontal steel brackets are fitted to the bulkheads & the thickness of the lower stiffeners of bulkhead N° 155 & the lower deck stiffeners of bulkhead N° 126 are as approved. The Side Guide top angles are as required by the Rules and not as stated but the Surveyor should be requested to state if this is so; they should also be requested to state the number

Angles on upper edge _____ Deck. Material and thickness _____

of bulkheads extending to the Shelter Deck and to the Upper Deck.

PH



© 2021

Lloyd's Register
Foundation