

Surveyors

Received from Chief Surveyors

NAME Steel & S. "BEN SEYR"
etc "DEVERON"
Report LIU. No. 80758
For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.

Survey When due

☒ 100 A.t. (steel)

1 Dk (steel) "Well Dk."

FPT 12t APT 30t


BK 7½' 3 BH. Cem. Lloyd's A9C.P. A 41', B 29', F 20'

Date of Build 4, 20.

Wachy. aft.

The Certificate of Classification, to be endorsed
 "Cargo battens not fitted," and the same
 notation to be printed in the Register Book.

It is concluded, that ^{see if the rivets in the} the ³/₄ rivets in butts of shell plating are spaced
 3½ diameters apart as required, ^{but} ⁸ but the Surveyors should be requested to state
 if this is so.



W425-0007

W425-0008

Lloyd's Register
FoundationInches
in Ship

to

—

—

3½

2½

the

3

—

•28

3

—

—

—

ne

3

—

3

—

3

—

44

18

3

—

10

—

28

3

—

28

3

—

18

3

—

6

—

5

—

4

—

5

—