

### No. in way of Double Bottoms at Solid Floors..

Quarter 'tween Dks.

42m.12.18.

*Received by Chief Ship Surveyor.*

*Received from Chief Ship Surveyor*

VESSEL'S NAME Steel S.S. "WEST WAUNA". Rpt. Pld. No. 546

**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

### Nature of Survey

The kedge anchor has been dispensed with as a War Emergency Measure at the Owners' request.

✠ 100 A.1. (Steel).

2 Dks. (Steel).

Cell DB 356' 1139t. MT 29' 745t. FPT 132t. APT 143t.

FK. 7 BH. pt. Cem. A. & C.P. P44', B115', F47'.

25. 3. 19

Lloyd's Register  
Foundation

W 427 - 0102

<b>BEAMS, Upper Deck, Single Angle, Bulb</b>	
<b>Angle, Plate, Tee Bulb, or Channel</b>	
In way of Long Bridge .....	

7	3-438	18-6	7c	3-438	18-6
	✓	✓		✓	

**Fourth and Fifth Deck Stringer Plate,**  
breadth & thickness