

22 OCT 1935

No. 22869

REPORT of SURVEY for REPAIRS, &c.

of writing Report.

When handed in at Local Office 21. 10. 1935.

Port of BARRY.

Survey held at Book.

on the Wood, Iron or Steel S.S. "CHARLBURY"

TONNAGE —

Gross 6030.

Net 3902.

BARRY.

Date, First Survey 14/10/35 Last Survey 21. 10. 1935.

(No. of Visits 4)

YEAR. MONTH.

Built at Newcastle. By whom constructed Whitworth & Co. When 1906. 9

Owners T. & G. Green Shipping Co. Ltd. Owners' Address

(if not already recorded in Appendix to Register Book).

Managers B. & S. Shipping Co. Ltd. Port belonging to London.

Repaired Afloat or in Dry Dock? Name of Dock Barry Docks. Destined Voyage

= Cell D or DBa feet; uE&B feet; f feet | l capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, &c., and of the inner bottom plating, especially in the boiler space.

1st Report, No. 106135 Port His

Medical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the work of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the agreement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided back of this form. State also the dates and initials of any letters respecting this case 106135-82.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

UNDERTAKING CASE
Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? If so, by whom?

AIRS, OR EXAMINATION AS PER RULE, FOR General Examination.

DONE! A general examination made of the vessel afloat, the plates, decks, lower decks, M & BR spaces, bunkers (part coal), the decks, cargo rooms, hatches, hatch covers, ventilation, tanks & caging, general equipment. Windows, clearing engine & gear examined & steering gear tried. The vessel was found to be in a satisfactory condition for the intended voyage to Japan.

Repair: A. P. tank, an efficient cement to fit up bulkhead were really held.

Salvation Certificate issued. Copy herewith.

LIST OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fairied or Repaired								
Fairied or Repaired in place								

GENERAL CONDITION OF THE VESSEL

Good	State if Tanks have been examined inside	Yes.	Dblng. Plates under Sounding Pipes	Good.	Copper, or Y.M. of Wood Vessels
Eng. of Decks	State if Tanks now tested	No.	Engine Room Skylights	Good.	(State if on Feat.)
Engines	Bulkheads	Good.	Coal Bunkers, Open'gs, Lids, &c.	Good.	When put on, Month Year
& Fastenings	Ceiling	Good.	Scuppers	Good.	Boats
Plating	Cement or Asphalt	(State which.)	Cargo Hatchways	Good.	Masts, Yards, &c.
hooks	Rudder	Good.	Hatches	Good.	Condition, how ascertained
Comms	Steering gear and its connections	Good.	Planking of Wood Vessels	Good.	(State if wedges removed)
Plates	Windlass	"	Caulking ditto	Good.	Sails
Studs	Have Pumps now been examined and found efficient?	"	Treenails ditto	Good.	Equipment letter Z
Verins	Have Sluice Valves now been examined and found efficient?	"	Breasthooks & Stemson ditto	Good.	Anchors, No. of 318. 18.
Comms	Have Watertight Doors now been examined and found efficient?	"	Transoms, Pointers, & Crutches ditto	Good.	Cables (State if now ranged)
Plates	Have Ventilators and their Comings been examined and found efficient?	Yes.	Timbers of Frame at openings ditto	Good.	,, length (on board) size
Bottom Plating	and found efficient?		Ditto ditto at other places ditto	Good.	,, Rule length size
			Stringers, Clamps & Shelves ditto	Good.	Hawsers & Warps sufficient
			Salting ditto	Good.	Standing and Running Rigging Good.

GENERAL OBSERVATIONS, OPINION AS TO CLASS, RECOMMENDATION, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey 1-24," or "to remain as classed and to have record of survey 1-24, and the notations of ss. No. 1-24 and ptnd24, &c."

This vessel as far as can be judged in my opinion is to remain as now classed without fresh record, subject to the vessel being broken up at the termination of her present voyage to Alexandria with coal & coke. On another occasion perhaps to Japan with a cargo of coal or mineral.

Survey Fee (per Section 29)	£	:	:	Fees applied for,
General Exam.	£	8	8	0
Special Damage or Repair Fee (if any) (per sec. 29)	£	18/10/1935	Q	
Arranging Expenses (if chargeable)	£			Received by me,
Second Surveyor's Fee (if any)	£			21. 10. 1935

Committee's Minute

Character Assigned Deferred W.H. 1936

For R. Dept.

UNDERTAKING CASE

Is certificate required? If so, to be sent to

FRI. 25 OCT 1935

FRI. 19 MAY 1936

2020



Lloyd's Register Foundation

W490-0020