

24 FEB 1936

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report: 31st Jans. 36 When handed in at Local Office 31st Jans. 36 Port of Singapore
 No. in Reg. Book Survey held at Singapore Date First Survey 18th Jans. Last Survey 30th Jans. 1936
 22359 on the Machinery of the Wood, Iron or Steel T.S. CARNARVONSHIRE (No. of visits 5.)
 Tonnage Gross 9385 By whom Workman, Clark & Co. Ltd.
 Net 5886 Vessel built at Belfast When 1914 - 3
 Nominal Horse Power 977 Engines made at " When 1914 "
 No. of Main Boilers 204 (Donkey) ✓
 258 Owners Address
 0. of Donkey Boilers 1
 Steam Pressure in Main Boilers 200 lbs. Port Belfast
 in Donkey Boilers 1 Voyage Japan.
 If Surveyed Afloat Yes.

Last Report No. 40253 Port Gul

Particulars of Examination and Repairs (if any) Boiler Examination.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and cases being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case. ✓

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

as a damage report made by anyone else? If so, by whom? ✓

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ✓

Donkey "

This was not done, state for what reasons? Boilers not prepared for survey.

What parts of the Boilers could not be thus thoroughly examined? ✓

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

The latest date of internal examination of each boiler. ✓

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER For Special Survey Date of last Survey and of Periodical Surveys.	Machinery and Boiler Survey (including date of N.B. if any).
+100A1	+L.M.C. 5.34
S.S. Ham. 112 3-4, 26	C.L. 10.34
S.S. Ham. 112 1-30	Sloyd's R.M.C. 3.35.
Mab 1.34	
FITTERS & M.L. FUS.	
B.P. ABOVE 1500' A.	

Present condition of funnel(s) ✓

160 lbs/in²

To what pressure were they afterwards adjusted under steam? ✓

To what pressure were they afterwards adjusted under steam? ✓

and of the Donkey Boilers? ✓

and of the Donkey Boiler? ✓

and of the Donkey Boiler? ✓

Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated? ✓

Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated? ✓

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft. ✓

Is electric light and/or power fitted? ✓

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

general examination was made of the starboard forward (S.B.) and port aft (D.B.) furnaces on the 18th and 19th January, 1936, and it was recommended that these two furnaces be thoroughly cleaned in way of the combustion chambers and that the air and water spaces be cleared of all loose dirt. The port furnaces of the starboard aft (D.B.) were both badly distorted and, as arrangements had been made for the vessel to proceed at reduced speed to Japan no repairs were carried out to this boiler and it was recommended that it should not be put into service again. The port forward (S.B.) was examined under steam and found to be in satisfactory condition; it was stated that no trouble had been experienced with this boiler on the passage to Singapore.

When the cleaning of the two boilers had been completed, an examination was made of the fire and water sides and (see continuation sheet)

General Observations, Opinion, and Recommendation:—The machinery of this vessel is

state clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9/11, B.A.M.S. 9/11, +L.M.C. 9/11, or G.L.M.C. 11/10, F.D., &c.)

OS 2/24,

It is desired to advise the Surveyor that the machinery of this vessel is to be reclassified in the Register Book, consequent upon the survey, and the record of survey subject to the starboard aft boiler not being used and the boiler pressure being reduced to 160 lbs/in².

(per Section 20) \$10.00
 B.1.-10
 Age or Repair Fee (if any) _____
 (per Section 20) _____
 Travelling expenses (if chargeable) (B.O.R.T.) \$24.35

Fees applied for
 30/1/1936
 Received by me,
 10

Committee's Minutes TUE. 3 MAR 1936

Assigned Deferred

Note for press

Printed

To be broken up
 white oak
 (Note for R. Dept.)


12th March 1936

John Wormald

Engineer Surveyor to Lloyd's Register of Shipping

Is a Certificate required? If so, to be sent to

2020



Lloyd's Register

W490-Foundation

Port of SingaporeContinuation of Report No. 5789, dated 31st Janv. 1936, on theT.S.S. "CARNARVONSHIRE."

the following repairs were recommended, and subsequently carried out :-

Starboard forward boiler :-

3 saddle rivets to cut, out, and renew.

8 open cracks in way of saddle rivets to cut, out, and weld.

9 tube stoppers to cut, out, and rejoint.

1 c.c. back stay to re-caulk, and nut to renew.

About 100 smoke tubes to re-expand.

About 15 forced-draught air tubes to renew.

Boiler to be tested hydraulically to 200 lbs/², and all leakages to be made tight.

Port aft boiler :-

11 saddle rivets to cut, out, and renew.

15 open cracks in way of saddle rivets to cut, out, and weld.

15 tube stoppers to cut, out, and rejoint.

1 crack on starboard forward furnace to weld.

2 cracks, on forward tube plate of centre furnace to cut, out, and weld.

About 150 smoke tubes to re-expand.

About 30 forced-draught air tubes to renew.

Boiler to be tested hydraulically to 200 lbs/², and all leakages to be made tight.

The two boilers were tested on the 28th January, 1936, and were found to be tight but in view of the generally distorted condition of the tube plates and back plates of the combustion chambers of the single-ended boiler, it was recommended that the steam pressure be not allowed to exceed 160 lbs/², and the safety valves of the two forward boilers, and of the port aft boiler were adjusted to that pressure.

J. W.