

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 106066

 (Received at London Office) -2 OCT 1935
 When handed in at Local Office -26 SEP 1935

 Survey held at Liverpool Port of LIVERPOOL
 Date, First Survey 11/9/35 Last Survey 17/9/1935
 (No. of Visits 3)

 on the Machinery of the Wood, Iron or Steel ELSFIE ANNIE

 Gross 358 Vessel built at Newcastle By whom Wood Skinner & Co. Ltd. When 1904-12mo

 Net 141 Engines made at do By whom A. E. Marnie & Co. Ltd. When 1904

 Boilers, when made (Main) 1932-4 (Donkey) ✓

 Owners Wesford Steamships Ltd. Owners' Address Wesford

 Managers J. J. Stafford (if not already recorded in Appendix to Register Book.)

 If Surveyed in Dry Dock Clarence Dry Dock Port Wesford Voyage

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

 Port No. Port

 Years of Examination and Repairs (if any) TS & Repairs

When held, must be reported in detail and serially in the terms of the Rules. State clearly the nature, if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on the machinery (the cause of which must be stated) should be separated from Repairs due to other causes; and details of any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he has made a special damage report he is required to state whether he

 services for this purpose, and why they were declined ✓

 report made by anyone else? If so, by whom? ✓

 personally go inside each Main Boiler separately and make a thorough examination at this time? ✓

 " Donkey " ✓

 one, state for what reasons? ✓

 of the Boilers could not be thus thoroughly examined? ✓

 means, in the absence of internal examination, were adopted by the ✓

 sure himself of the thorough efficiency of those parts of each Boiler? ✓

 of internal examination of each boiler ✓

 Present condition of funnel(s) Good

 examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

 examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

 examine all the manholes, doors and their fastenings of the Main Boilers? ✓ and of the Donkey Boilers? ✓

 examine the drain plugs of the Main Boilers? ✓ and of the Donkey Boiler? ✓

 examine all the mountings of the Main Boilers? ✓ and of the Donkey Boiler? ✓

 now been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No

 been changed? No If so, state reasons ✓

 now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

 Examination of Screw Shaft 12/9/35 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft rewooded

 Is electric light and/or power fitted? ✓

 not complete, state what arrangements have been made for its completion and what remains to be done Complete

ne: Vessel placed in dry dock, propeller and outside fastenings

id. Screw shaft (CL) drawn & examined.

ank pin found to be slack. Crank shaft removed and a new crank

ted (Stamped Lloyd's No. 2052 17/9/35 H.C.M.). Crank shaft refitted and alignment

. HP Piston rod renewed.

 Observations, Opinion, and Recommendation:— The Machinery of this Vessel
 what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book consequent upon this survey, and also
 140 lb., F.D., &c.)
as now seen is in safe working condition and is eligible in my opinion
as classed without fresh record of survey and to have notation of
shaft seen CL 9.35

 Fees applied for 27 SEP 1935
 Repair Fee (if any) £ 3 : 3 : 0
 Received by me 14/10/35
 (if chargeable) ✓
 1 OCT 1935

 H. B. Murray
 Engineer Surveyor to Lloyd's Register of Shipping.

 As now.
 T.S. 9.35: CL
 W494-0180

 Lloyd's Register
 Foundation

