

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 77665

TUE 18 MAR. 1924

Date of writing Report	10	When handed in at Local Office	13/3/24	Port of	NEWCASTLE-ON-TYNE	
No. in g. Book.	Survey held at Willington Quay.		Date, First Survey	16 Jan.	Last Survey	13 March 24
892	on the Machinery of the Wood, Iron or Steel Co. & Met. Sv.		(No. of Visits)			10
Gross 665		PYLADES				
Net 278		Vessel built at Willington		By whom R. Williamson & Son	When 1903-9	
Nominal orse Power 85		Engines made at Glasgow		By whom Ross & Duncan	When 1903	
o. of Main Boilers 1		Boilers, when made (Main) 1920 Fitted 1921		(Donkey)		
o. of Donkey Boilers ✓		Owners Mr. Taylor		Port Methil	Voyage	
team Pressure— in Main Boilers 160		If Surveyed Afloat or in Dry Dock Cleland's Slipway		Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).		
in Donkey Boilers ✓		(State name of Dock.)		CHARACTER. For Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (including date of N.B., if any).	

Last Report No. Port

Particulars of Examination and Repairs (if any) L.M.C.

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined?	Was a damage report made by anyone else? If so, by whom?	SEE LIMITATION LIST.	
the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?		Donkey boiler not to be used again.	
Do. " Donkey "	"	No (new Bale fitted)	
his was not done, state for what reasons?		None (old D Blr. removed ashore)	
what parts of the Boilers could not be thus thoroughly examined?		✓	
what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?		✓	
the Surveyor examine the Safety Valves of the Main Boiler?		Yes To what pressure were they afterwards adjusted under steam?	
the Surveyor examine the Safety Valves of Donkey Boiler?		✓ To what pressure were they afterwards adjusted under steam?	
the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?		Yes , and of the Donkey Boiler?	
the Surveyor examine the drain plugs of the Main Boilers?		None , and of the Donkey Boiler?	
the Surveyor examine all the mountings of the Main Boilers?		Yes , and of the Donkey Boiler?	
screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes		Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No	
shaft now been changed? No If so, state reasons		✓	
the shaft now fitted new? ✓ Has it a continuous liner ✓		Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓	

the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft? A good fit - low wood now renewed.

the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete.

examined cylinders, pistons, cross, slides, crank, thrust & screw shafts, condenser, air, circulating, feed and bilge pumps with their connections, propeller, sea connections and side fastenings, the steering engine rudder.

The main & Donkey Boilers were disconnected and lifted ashore and a new main Bale fit by means the Central Marine Engine Works Certificate No. 3594 for which a copy of the spot is attached hereto, was efficiently installed. The manifolds were all tested by hydraulic pressure. The main Steam pipe, the feed and blow down pipes were annealed and set by hydraulic pressure. Two spring loaded safety valves of total area 16.59 sq" fitted with earing bar, were mounted and adjusted under steam. The distance between the Bale shell & the side bunkers is 12'. The Bale is coal-fired. It is stamped FITTED 3.24 R.L.A.

The H.P. piston valve liner was bored and a new piston valve fitted. The H.P. & L.P. piston rings were renewed.

Thrust shaft collars were renewed and all re-metalled. New feed pump plungers were fitted.

General Observations, Opinion, and Recommendation:— The machinery of this vessel is now

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.11, B.M.S. 9.11, or L.M.C. 9.11, 140 lb., N.B., &c.)

In good order & eligible, in my opinion, to remain as classed with records of

L.M.C. 24 + N.B. 21 FITTED 3.24 Screw shaft seen C.L. 3.24

Survey Fee (per Section 28)

£ 7 : - -

Fees applied for

Initial Damage or Repair Fee (if any)
(per Section 28.)

£ 5 : 5 : -

19

Welling Expenses (if chargeable)

£ : - -

Received by me,

24/3/24

G.J. 66

R. Lee Ames

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute TUE. 25 MAR. 1924

Assigned to Mr. 6. 3. 24

Without Spec Cond
+ N.B. 3.24 to

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to

S.S. PYLADES (Contd.)

The bilge pump rooms were skimmed and re-tubed. The feed & life suction + delivery valves' chests were overhauled and put in order. The Ballast + General Service pumps were repaired. The Condenser tubes were drawn, the condenser cleaned, relubed and tested.

A careful examination was made of the No. 5 journal of the Crank Shaft - see Smith Report No. 16067 - the shaft is an iron forging and the marks on it are all longitudinal. There was no exudation of oil on hammering and the marks appear to be of a superficial character. There has been no extension since the limits were marked in Jan/Feb 1922 and it is respectfully submitted that the vessel's name should now be removed from the limit list in respect of this shaft. The entry in the Special Reasons list with respect to the Donkey Boiler, which has now been put ashore may now be deleted.

Ref Armee.

Mr. H. J. due 2.23 held old main donkey boiler turned
from vessel to new main boiler fitted limit 2
to 0.5 general grant of crank shaft expanded shaft
and satisfactory. Several up-to-date effects
of which recently drawn

It is submitted that
this vessel is eligible for
THE RECORD + L. m. C. 3.24 without
special restrictions

OS 3.24 + N.B. 3.24 3c
G.J. 52. P.I. 1934 N.H.R. 10 (5)

H.
24/3/24



© 2020

Lloyd's Register
Foundation