

Subject to indented shell plate F3 starboard side being repaired at the first convenient opportunity.

10.35.

Jan 10 29 20

11

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

13 11 1935

SEL'S NAME

M. S. "WEXFORDIAN"

Rpt.

bff

No. 57123

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

ve of Survey

The

Cardiff

Surveyors report this vessel placed in

dry dock, bottom cleaned and coated and minor repairs effected.

The indented shell plate as above, not dealt with, but remains efficient.

It is submitted the vessel appears worthy to remain as

classified with record of survey 8-35 ^{subject as above} as recommended.

100A1 } Subject etc
8-35 bff

M.B.

10.8.35



© 2020

Lloyd's Register
Foundation

WS'29-0196