

FRAMES, DOUBLE BOTTOM AND BEAMS.

SHIP.

2m. 1224.

1

Sent to Chief Surveyors _____ Received from Chief Surveyors _____

VESSEL'S NAME Stk Sc. ANNIE M. MILLER. Report Exp No. 18943

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey 1st Entry When due _____

1/4. 100 A. 1. (Stk).
1 Sk. (Stk). Wely aft.
Cell SB in E 18' & 88' 1586. FPT 506. APT 66.
FK. 3BH. Com. Lays A & CP.
RQD 55' F 37'

Revised Rules.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2021

W.M.A.
16. 8. 28.

Lloyd's Register
 Foundation

W638-0013

DOUBLE BOTTOM.

Floors Depth and thickness at mid-line in)

Uppermost Continuous Deck, amidships }
 in Wells, Angle, E or F
 in rear of Bridge, Angle

32 3 30