

COPY.

Lloyd's Register of Shipping.



Port HULL.

19th July, 1940.

This is to Certify that

W. S. SHIELDS and N. C. JUNIPER,

The undersigned Surveyor^s to this Society did at the request of the Netherlands Shipping & Trading Committee, survey the steamer "OOSTPLEIN", 5059 tons gross of Rotterdam, formerly classed with Germanischer Lloyd, on the 21st June, 1940, and subsequently, and that the following parts of hull and machinery were examined
float, viz:-

Fore peak tank internally, forepeak spaces, plating under sidelights, Nos. 1, 2, 3, 4, 5 holds.

Midship deep tank, internally.

Aft deep tank internally.

Fore peak tank internally, aft peak spaces.

Double bottom tank internally under main boilers.

Engine and boiler spaces, under engines and main boilers.

Foreboard deck, (except in bridge space), forecastle bridge and poop decks.

Stairways and hatches, (except in way of bridge space), coamings, davers supports, tarpaulins, cleats, wedges, and battening arrangements.

Windows, ventilators and coamings.

Windlass, steering gear, W.T. doors.

Wires, rigging, air and sounding pipes (partly.)

Lifeboats.

Revised freeboard and amended lettering to L.R.

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, but it shall be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any other publication of the Society, or for any error of judgment, default or negligence of any of its Members thereof, or the Surveyors, or other Officers or Agents of the Society."

ed fore end after peak tanks, aft deep tank and all D.B. tanks,
ot dry D.B. tank under boilers and D.B. tank under engines.

Repairs:-

port side stringer bracket of aft bulkhead, No. 5 hold.

a few shell rivets No. 2 hold.

ired No. 1 D.B.T. suction pipe, ps. in No. 2 hold.

Machinery - Examined.

main boilers complete.

engines H.P. cylinder, M.P. and L.P. valves.

, M.P. , L.P. bottom ends, top ends.

shaft journals, Nos. 1 & 3.

mediate shaft (1st length in tunnel.)

ard independent feed pump.

al service pump.

ing arrangements.

nder of machinery generally examined.

Repairs:-

renewed stays of boilers renewed.

ain plugs of boilers renewed.

that we have transmitted to the Committee of Lloyd's Register
Shipping, London, a report stating that all repairs recommended
have been completed to our satisfaction, and that we have
recommended that she be assigned a notation of EXAMINED L.R. 7,40,
stating that from the parts now seen she appears to be in an
satisfactory condition for a period of six months from date (7,40.)

S. Shields & H. Clive Juniper.

SURVEYORS TO LLOYD'S REGISTER OF SHIPPING.



© 2019

Lloyd's Register
Foundation

W64-0375 2/2