

^ engine room aft.

are then clear of all inflammable material *no*

am, 5/31.

to Chief Surveyors

Received from Chief Surveyors

tested as
ident.

VESSEL'S NAME

British Gore

Report

*Line.*No. *100096*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ure of Survey

When due

*Elec. Light installed.
record Elec. Light*

Noted

*LL
✓ 11/4/32.*



© 2021

Lloyd's Register
Foundation*W 664-0275*

arth Testing, state what means are provided at the main switchboard for indicating the state of the insulation of the system

work fitted