

new length of cable placed on board, markings verified (see over). ...
... fitted where missing in 3 lengths of cable. 3 shackle-pins renewed.

W699-0138

3m, 1.23.

17 DEC 1923

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl.s.s. "FERONIA"

Rpt. Npt. No. 20930

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey


The class of this vessel is subject to some indented bottom plating being dealt with.

The Newport Surveyors now report the vessel placed in dry dock, the bottom cleaned and coated, one shell plate renewed, three plates repaired, 15 fathoms of chain cable of proper size, weight and test supplied, the stream anchor retested, and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 12,23, without special condition, as recommended.

100 A1 } Without etc.
12-23 Npt.

PLATING TO BE DRILLED when vessel 10-24 years old, extract special survey thermometer.



per Sec. 20)

ing Expenses (if chargeable)

Received by me,

11 Dec 1923

J. L. Dwyer

Surveyor to Lloyd's Register of Shipping.

Year
No
No
size
size
Good
sequent up
ve record
Bo