

How done - Vessel placed in the dry dock & the hull

W706 - 0216

27 AUG 1921

3,500,11,20.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sc. "RIVER TEES". Rpt. sld. N028136

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

The Sunderland Surveyors report this vessel has been placed in dry dock after grounding, bottom and rudder cleaned and coated, rudder lifted and 2 shell plates removed, faired and refitted and 2 plates, 11 frames and 6 floors faired in place, and minor repairs effected. Other repairs have been effected as follows:- lower bridge and forecastle decks and deck over the engineers' accommodation recaulked and a few minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey.

100A-1
8-21 SLS



© 2021 Lloyd's Register Foundation

26. 8. 21.

as classed & to have record of Survey 8.21.

Wood Vessel
nth
retained
s removed
3B
ow ranged
g Rigging
Book conse
and to hav

been hel
sent nos
nk.
low the space fo