

Deck	Fect.	Inches.	BREADTH—	Fect.	Inches.	DEPTH, ACTUAL—	Top of Floors to top of Upper Dk. Beams	Fect.	Inches.	No. of Decks with flat laid
....	184	0	Moulded	31	0	Do. do. do.	BRIDGE Second Dk. Beams	20	9 3/4	No. of Tiers of Beams
						Moulded depth, ft. 21 ins. 6	To Bridge Dk.			Round of Upper
						17 ins. 6	To Upper Dk.			Dk. Beam, Actual

Chief Surveyors

EL'S NAME

B. S. "Lismore"

Received from Chief Surveyors

Report

Glb

No. 43774

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

of Survey

1st Entry

When due

+ 100 A1 (Steel)
1 Dk. (stl.)

Cell DB v E 9' 13". f 20' 36". F.P.T. 35". A.P.T. 11".
F.K. 8 B.K. 1 1/4" 4 B.H. rem. Lloyds A. & C. P.
P. 28' B. 68' F 64'

[Signatures]

47-24

Lloyd's Register Foundation

in Engine and Boiler space	36	34	28	28
Remainder in Holds.....	(ER-34)	28	28	28
er Deck, Single Angle, Bulb	7	3	42	7
angle, Plate, Tee Bulb, or Channel	6	3	42	6
way of Long Bridge	44	44	44	44

Tie Plates, outside Hatchways.....
Deck.* Material and thickness
Fourth and Fifth Deck Stringer Plate, } breadth & thickness
Angles on ditto, No.