

THE 2ND S.S.N^o1 BECAME DUE 8-39
EXAMINED 10-40-12 MONTHS EXTENSION.

13 FEB 1941

Report to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME POLITICIAN Report LIV No 115532

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE When due.....

Buckled stem + stem plating require to be permanently repaired at the Owners convenience

WAL
12.2.41

The Certificate of Classification to be endorsed "Cargo battens not fitted" **IN SHELTER TWEEN DECKS** and the same notation to be printed in the Register Book.



© 2019

Lloyd's Register Foundation

W72-0073