

Report of Survey for Repairs, &c., of Engines and Boilers

(Received at London Office **FRI. 5 JUN 1908**)

Date of writing Report 19 When handed in at Local Office 4/6 10 08 Port of **GRIMSBY**

No. in Reg. Book. Survey held at Grimby Date, First Survey 28. 5. 08 Last Survey 2. 6. 1908 (No. of Visits Two.)

157 on the Machinery of the ~~Wood, Iron or Steel~~ Sc. K. Washington Master

Gross 264 Net 121 Vessel built at Selby By whom Cochran & Sons When 1907 #

Registered Horse Power 70 Engines made at Hull By whom E. D. Holmes When 1907

No. of Main Boilers 1 Boilers, when made (Main) 1907 (Donkey) ✓

No. of Donkey Boilers ✓ Owners Premier P. Z. & Co. Port Grimby Voyage Fishing

Steam Pressure 180 If Surveyed Afloat ✓ in Dry Dock fish.

No. in Donkey Boilers ✓ Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. Port

Particulars of Examination and Repairs (if any) Docking: -1-100A1

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

CHARACTER, &c. for Special Survey. Date of last Survey and of Periodical Surveys.	Years since last survey. (If not applied, state when applied.)	Machinery and Boiler Surveys (including date of N.B., if any).
<u>Stm. Tranker</u> <u>4,07.</u>		<u>1-2 M.C. 4,07.</u>

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? ✓ also whether any damage report was made, and, if so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " "

this was not done, state for what reasons?

what parts of the Boilers could not be thus thoroughly examined?

what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boiler?

the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

screw shaft now been drawn and examined? NO Is it fitted with continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

shaft now been changed? ✓ If so, state reasons ✓

the shaft now fitted new? ✓ Has it a continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

the distance between lignum vitae of stern bush and top of after bearing of screw shaft? Good fit.

the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete.

The propeller, sternbush and sea connection fastenings examined
A patch at the back end of the starboard bottle mouthed furnace repaired.

General Observations, Opinion, and Recommendation:— This vessel is eligible in my opinion to remain as classed without fresh record of survey.

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 0,07, B.&M.S. 0,07, or L.M.C. 0,07, 140 lb., F.D., &c.)

Survey Fee (per Section 25)..... £ : : Fees applied for

Special Damage or Repair Fee (if any)..... £ : : 19

(per Section 25.)

Surveying Expenses (if chargeable)..... £ : : Received by me, 19

Charles E. M.
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Minor repairs to boiler effected.

It is submitted that
this vessel is eligible to
remain as CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

JWD
5/6/08

See Table

in ship's a lower side
paints brass leaf finish
boards as inner of inner

main compartment
between other plates at
bottom of compartment

See Table

See Table

See Table

See Table

See Table

See Table

See Table

See Table

See Table

See Table

See Table

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020
Lloyd's Register
Foundation