

Received by Chief Ship Surveyor 24/8/08.

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME St. S. S. "Civo"

Rpt. Stul

No. 20448.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>1 1/16 in lieu of 8/20.</u>	<u>not required</u>
Spar Sheerstrake . .		
Description of Framing:— <u>Ordinary, increased to compensate for</u> (viz., ordinary, deep, zed, channel or bulb-angle). <u>omission of reverse frames.</u>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed +100 A.1. ("Steel") "Steam Trawler" as recommended.

+100 A.1. ("Steel") "Steam Trawler"  
1 Dk.

B.K. 7 1/2" 4. B.H. Com Lloyds A. & C.P. 944' F 23'



© 2021  
C.M.J.  
Lloyd's Register  
Foundation

BC  
24/8/08

It is concluded the reverse bars are not fitted when the floors are cemented up but the Surveyors should state if this is so.

W 781 - 0094