

TUE. MAR. 10. 1914

(Received at London Office)

No. 9387

REPORT of SURVEY for REPAIRS, &c.

of writing Report... 19... When handed in at Local Office 9.3. is 14 Port of GRIMSBY
o. in Survey held at GRIMSBY Date, First Survey 6 March Last Survey 7 March 1914
Book. (No. of Visits two)

On the Wood Iron or Steel S.C.H. "OKINO" Master
TONNAGE:- Built at Selly By whom Cochrane & Sons L^a When 1913
GROSS 225 Owners H. L. Taylor Port belonging to Grimsbay
UNDER DEK... Owners' Address Grimsbay
NET... (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Both Name of Dock Fish Destined Voyage Fishing
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER: 100 A1.
STM. TRAWLER
Machinery and Boiler Surveys (including date of N.B., if any).

CLASS CONTEMPLATED
Society's Freeboard (if assigned) as 17.2.12 & 7.3.14 painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition & Equipment

How Done:- Vessel placed in dry dock; Bottom cleaned, examined and recoated.

New Bower anchor placed aboard in place of one underweight
for particulars please see other side.

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks <u>Good</u>	Inner Bottom Plating	Engine Room Skylights <u>Good</u>	(State if on Fell.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats <u>Good</u>
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained <u>From PK</u>
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder <u>Good</u>	Caulking ditto	Sails
Rivets	Steering gear and its connections	Treenails ditto	Equipment letter
Breasthooks & Crutches	Windlass	Breasthooks & Stemson ditto	Anchor, No. of <u>2B. 1K.</u>
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	Rule length size
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Rule length size
Floors		Stringers, Clamps & Shelves ditto	Standing & Running Rigging <u>Good.</u>
Keelsons		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and ptND11, &c."

The above is forwarded for the information of the Committee.

Survey Fee (per Section 99)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 99)	£	10
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	10

Gloof J. J. J.
Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute
Character Assigned
100 A1
Stm Trawler



W807-0111

W807-0115

