

No. 77176

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office WED. 5-DEC-1917)

of writing Report	17 NOV 1917	When handed in at Local Office	17 NOV 1917	Port of	LIVERPOOL
in Book.	Survey held at Liverpool		Date, First Survey	Last Survey	Nov 14, 1917
Suf. on the Machinery of the Wood, Iron or Steel S/s <i>Justicia</i>				No. of Visits	
Gross	32234	Vessel built at Belfast	By whom Harland & Wolff, Co.	Master	YEAR. MONTH.
Net	19801	Engines made at Belfast	By whom Harland & Wolff, Co.	When	1917 4
stered Power		Boilers, when made (Main) 1917	(Donkey)	When	1917
Main Boilers	12	Owners Oceanic Iron Nav. Co. Ltd. (White Star Line) Port Liverpool	Voyage		
Donkey Boilers	0	If Surveyed Afloat or in Dry Dock Gladstone Dock - Dry			
Pressure Main Boilers	215 lb	(State name of Dock.)			
Donkey Boilers					

Report No. Port

Particulars of Examination and Repairs (if any) Dry docking

Medical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and the cost being detailed in the body of the report, should be briefly summarised at the end of the report. State also the name and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

O. " Donkey " " "

Was not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam?

Did Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam?

Did Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓ , and of the Donkey Boiler?

Did Surveyor examine the drain plugs of the Main Boilers? ✓ , and of the Donkey Boiler?

Did Surveyor examine all the mountings of the Main Boilers? ✓ , and of the Donkey Boiler?

Has screw shaft now been drawn and examined? ✓ Is it fitted with continuous liner? ✓ or two liners? ✓ or is it without liners?

Has shaft now been changed? ✓ If so, state reasons. ✓

Has shaft now fitted new? ✓ Has it a continuous liner? ✓ or two liners? ✓ or is it without liners?

The distance between lignum vitæ of stern bush and top of after bearing of screw shaft: 5 ft 0 in. 7/8 in. N. 5/8 in.

Is Survey not complete state what arrangements have been made for its completion and what remains to be done? Complete.

Where and when tested a Superintendent

The propellers, outer ends of stern bushes and fastenings of sea connection examined. Sea connections exhausted and examined.

When and where tested and Superintendent.

General Observations, Opinion, and Recommendation:— The machinery of this vessel, as (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.M. 9.11. B.M.S. 9.11, or & L.M.C. 9.11, 140 lb., F.B., &c.)

far as seen, is in good condition and, in my opinion, eligible to remain as classed without fresh record of survey.

Fees applied for
Survey Fee (per Section 28) £ 19
Special Damage or Repair Fee (if any) £ 19
Traveling Expenses (if chargeable) £ 19
Received by me, 19

B. G. Bedford

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute: LIVERPOOL 4 DEC 1917

Assigned as now.

Enter character of ship and machinery previously on the Register Book

If so, to be sent to

© 2018



Lloyd's Register
Foundation

It is submitted that
this vessel is eligible to
remain in the U.S.A. S.P.D.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.

S.M.
6.12.14.

WB19/20

• THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.