

F.E.

Inspected by Chief Ship Surveyor

27.11.13

Received from Chief Ship Surveyor

VESSEL'S NAME

Hulls Lord Londesborough

Rpt.

Incl

No.

26953

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

36.12

Depth "d"

11.67

Framing: Table No.

3 page 9

Description

Single angle as approved

Longitudinal No.

4936.

Proportions

Length =

10.5

Depth =

~~Deck~~ Sheerstrake . 62 of an inch instead of . 38 as required

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A-1 (Steel) "Steam Trawler" as recommended.

∇ 100 A-1 (Steel) "Steam Trawler"

1 Dn.

BK $7\frac{1}{2}$ 4 BK. Cen. Lloyd's reg. Q 74' F 19'.

The Surveyors should be requested to state the spacing of the horizontal & vertical stiffeners on midship bulkheads as this has been omitted from the report.

M
27.11.13

© 2021 Lloyd's Register Foundation
M
27.11.13
W1826-0053