

1

Sent to Chief Surveyors 14. 2. '18

Received from Chief Surveyors


VESSEL'S NAME Steel S. S. Lowther Range Report Ph. No. 31451

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Damage When dueNotes

The class of this vessel should be subject to the stem and forward shell plating on starboard side being permanently repaired at first favourable opportunity, as per Lth. Rpt. 15 Oct.

15. 2. '18

© 2020

Lloyd's Register
Foundation

being fit to carry

Cables (State if now ranged

" length
(on board)