

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 13 SEP 1949)

Writing Report 1st July 1949 When handed in at Local Office 2nd July 1949 Port of Newport
Survey held at Newport Date, First Survey 9th June Last Survey 20th June 1949 (No. of Visits 3)

on the Machinery of the ~~Wood, Iron or Steel~~ M.V. BRITISH MERCHANT
Gross 7012 Vessel built at Glasgow By whom W. Beardmore & Co. Ltd. When 1922-11.
Net 4004 Engines made at Ldo. By whom - do. When 1922
Main Boilers 3. Boilers, when made (Main) 1922 (Donkey) 1922
Owners British Tanker Co. Ltd. Owners' Address (if not already recorded in Appendix to Register Book.)
Managers Port London Voyage
Surveyed ~~Afloat~~ in Dry Dock Eastern Dock
(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey Date of last Survey and of Periodical Surveys.	Years assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+100A1 - 11-49	2/48	+LMC. 11-47
SS SHL. No 3. 3.35		BS. 10-48
SS FAL. No 1. 39.		TS(OG) 8-46
EXAMINED 10-48 (6 mos.)		
Carrying Petroleum in bulk		
Fitted for O.F. 10-22. F.P. above 150		

Report No. Port
Particulars of Examination and Repairs (if any) +LMC +docking

Repairs, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

Where cases where the Surveyor has not made a special damage report he is required to state whether he has declined his services for this purpose, and why they were declined

Has a special damage report been made by anyone else? If so, by whom?

Has the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Donkey " " " " No

As not done, state for what reasons? Not prepared for survey

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Latest date of internal examination of each boiler? Present condition of funnel? Efficient

Has the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of Donkey Boiler? Yes. To what pressure were they afterwards adjusted under steam? Not adjusted

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers? Yes

Has a new shaft now been drawn and examined? No Is it fitted with continuous liner? No Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? YES

Has the shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Latest date of examination of Screw Shaft? State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft.

When engine parts, when referred to by numbers, should be counted from forward. Is electric light and power fitted? Yes

Has the Surveyor examine the generators, motors, switchgear, cables and fuses? No

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? No

If the survey is not complete, state what arrangements have been made for its completion and what remains to be done. All Rule Requirements remain to be carried out. Sea Valves have been completed, no other repairs have been carried out, machinery has been boxed up + vessel is proceeding to another port to complete the survey

WORKING & COMMENCEMENT + LMC. Vessel placed in drydock Propeller + all underwater fastenings examined. All Sea Valves opened up, examined + found placed in good order.

The following items have been opened up, examined and recommendations made, but no repairs have been effected because of labour difficulties. Please see page 2.

General Observations, Opinion, and Recommendation:— The Machinery of this vessel so far examined is in an efficient condition, and eligible in my opinion to remain as now classed and to have the notation of +LMC and TS(OG) with date when the survey is completed

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, E.S.S. 9,11, & L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.) CS 2,24,

now seen is in an efficient condition, and eligible in my opinion to remain as now classed and to have the notation of +LMC and TS(OG) with date when the survey is completed

Survey Fee (per Section 20) £ : : Fees applied for 19

Special Damage or Repair Fee (if any) (per Section 29.) £ : : Received by me, 19

Printing expenses (if chargeable) £ : :

Committee's Minute

Signed

FRI. 21 OCT 1949

Deferred

Andrew J. Cant
Engineer Surveyor to Lloyd's Register of Shipping.



© 2020
Lloyd's Register
Foundation
1999-0130/2

Insert Character of Ship and Machinery precisely as in the Register Book

BRITISH MERCHANT (Page 2)

All sea valves, Main + Auxiliary Condensers Independent Bilge Pump, Weir's Dual Air Pump, Starboard Turbo Alternator (Turbinis gears) Inboard. (Port) 10KW. Dynamo Engine, Port Lub. Oil pump, Donkey Boiler Mountings, Main + Auxiliary Condenser (tested).

Recommendations made—

Independent Bilge Pump—Cylinder to bore out, new piston + rings to fit. New water end liner to fit, bucket to machine new rings to fit. Valves + valve gear to overhaul.

Evaporator—Relief Valve Casting (fractured) to be renewed, all mountings to overhaul, new fuel valve + chest to fit. New Baffle plate to fit. Boils to be annealed and tested; also spare set.

Weir's Air Pump—Piston Rods to machine both wet + dry rods to machine. Link pins to renew also brasses (to be all made same size).

Sea Valves—To completely overhaul. Low Main Injection new seat to fit. valve to machine. Donkey Boiler Blow Down valve new handle to fit.

Starb. Turbo-Alternator—1st Stage of Rotor Blading to reblade, diaphragms to remove for examination. Thrust collar to machine or renew.

All journals to hone, Governor gear to overhaul.

Port Dynamo Engine—(10KW) Top end pin to renew. Rods to machine, new Governor Valve to fit.

Port. Lub. Oil Pump—Combined Bucket + Piston Rod to machine if possible or renew. All group valve + seats to machine. Piston rings to renew. Bridle gear to renew (has been previously welded).

Donkey Boiler Mountings—All mountings to overhaul. Blow down chest + both fuel valve chest's seats + valves to machine.

Salinometer cock to renew. Safety Valve chest to be renewed (found wasted internally). Forward compression nut to be renewed (slack).

Main Condenser—Water box + Port door to renew. Starb. tube plate collar studs to renew.

Auxiliary Condenser—Both doors to renew. Water box to renew, after end tube plate to rejoin.

* NOTE. 2 doors for the Aux Condenser have been placed on order.

REPAIRS:— NOW EFFECTED:— The recommendations relating to the sea valves have been carried out.