

No. 63 Survey held at Weyford Date 25th January 1842
 on the Brig Ellen Master Capt. Shill
 Tonnage 94 tons Built at Princ Edwards Is When built 1825
 By whom built _____ Owners Mr Gaffney
 Port belonging to Weyford Destined Voyage Gloster
 If Surveyed Afloat or in Dry Dock Surveyed afloat
Liverpool 307. Weyford 6. Clapend

63
LTH

Length aloft 63 10 Extreme Breadth 19 8 Depth of Hold 10 11

Scantlings of Timber.	Inches.	Inches. Middle	Inches. Ends	Thickness of Plank.	
				Outside.	Inside.
Timber and Space..... each					
Floors..... sided	Moulded	<u>15</u>		Keel to Bilge	Foot Waling
1 st Foothooks..... "	"			Bilge Planks	Bilge Planks
2 nd Ditto..... "	"	<u>12</u>		Bilge to Wales	Ceiling in Flat
3 rd Ditto..... "	"			Wales	Ditto Bilge to Clamp
Top Timbers	"			Topsides	Hold Beam Clamps
Deck BeamsN ^o . of <u>24</u>	"			Sheer Strakes	Deck Beam Ditto.....
Hold BeamsN ^o . of <u>4</u>	"			Plank Sheers.....	Ceiling 'twixt Decks
Keel	"			Water-Ways.....	Hold Beam Shelves
Kelsons	"			Upper Deck	Deck Beam Ditto.....

Size of Bolts in Fastenings.		Iron.	
Copper.	Iron.		Inches.
Heel-Knee, and Dead Wood abaft	<u>Iron</u>	Bolts thro' the Bilge and Foot Waling	<u>1/2</u>
Scarphs of Keel.....N ^o .		Butt End Bolts	<u>3/8</u>
Floor Timber Bolts		Lower Pintle of the Rudder	<u>1</u>
Kelson ditto.....			
Transoms and throats of Hooks	<u>3/4</u>	} <u>all Iron</u> same in Iron above the Copper..... } <u>same</u>	
Arms of Hooks	<u>3/4</u>		

Timbering.—The Space between the Floor Timbers and Lower Foothooks in this Vessel is _____ Inches. The Space between the Top-timbers is 5 Inches. The Stem, Stern Post, are composed of English Oak the Transoms, Aprons, Knight Heads, Hawse Timbers, of English Oak and are new free from all defects. The Floors and first Foothooks are composed of all black birch with English oak Timber. new & these The other Foothooks and Top Timbers of Spruce with some English oak all through. The Shifts of the first and second Foothooks are not less than _____ N. B. When less than prescribed by the Rule, state how many. The rest of the Shifts of the Frame are _____ The Frame is _____ squared from the first Foothook Heads upwards, and _____ free from sap, and from thence downwards, the frame is _____

The alternate Frames are _____ bolted together. N. B. If not, state how bolted. The Butts of the Timbers are _____ close together; their thickness not less than _____ of the entire moulding at that place. The Frame is _____ chocked with _____ Butt at each end of the chock. The Main Kelson is composed of Black birch and the False Kelson of Red pine in one butt. The Scarphs of the Kelsons are not less than 5 feet 10 inches. one Scarph The Deck and Hold Beams are composed of Spruce the Hold beams yellow pine


Planking Outside.—From the Keel to the first Foothook Heads the Plank is composed of Red Elm From the first Foothook Heads to the Light Water Mark of Spruce From the Light Water Mark to the Wales of all Spruce The Wales and Black-strakes are of all Spruce The Topsides of Spruce The Sheer-strakes and Plank-sheers of Spruce The Water-ways of Spruce The Decks of yellow red pine new State of very good order The Shifts of the Planking are not less than _____ Feet _____ Inches. N. B. If less than prescribed by the Rule, state whether general or partial, and if partial, in what part of the Ship. The Planking is wrought _____ between

Planking Inside.—The Limber-strakes are composed of Elm the Bilge Planks of Elm and The Ceiling, Lower Hold, of yellow pine Between Decks of yellow pine new Shelf Pieces of _____ Clamps of Spruce

Fastenings.—To Hold Beams two Pieces to each beam well bolted Deck Beams two Pieces to each beam stringer Number of Breasthooks four breast Hook Pointers _____ Crutches _____ Butts End Bolts are of _____ in the Bottom, and _____ Bolt in each Butt End through and clenched. Bilge and Footwaling well bolted through and clenched. in side General Quality of Workmanship _____

We certify that the preceding is a correct description of the above-named Vessel.

Builder's Name _____
 Surveyor's Name W. P. Denny Surveyor



Her Masts, Yards, &c. are in Good condition, and sufficient in size and length.

She has SAILS.			CABLES, &c.		ANCHORS, and their weights.	
N ^o .		Fathoms.		Inches.	N ^o .	
1	Fore Sails,	130	Chain	one	2	Bower, ^{cut} 9 weight Each Chain Anchor
1	Fore Top Sails,	70	Hempen Stream Cable	5	1	Stream,
2	Fore Topmast Stay Sails,		Hawser		1	Kedge,
2	Main Sails,		Towlines			
2	Main Top Sails,	70	Warp	3		
and <i>is very well found in other Sails</i>			All of <u>Good</u> quality.			

Her Standing and Running Rigging all new - sufficient in size and good in quality.

She has one long boat Long Boat and one jolly boat

The present state of the Windlass is good Capstan _____ and Rudder all new

General Remarks—Statement and Date of Repairs.

This vessel is in the highest state of repair having had a general repair in Milford some time ago, about two years, new stem upons night heads & breast Hooks, little wise new stem frame & transoms, new decks, & two hold beams, new sailing all over caulked all over & treasels from keel to gunwale, about bolt in each but all through - & is stout staunch & strong fit to ^{take} cargo of dry & perishable goods to any part of Europe - This vessel is kept for the owners own use to carry grain to different parts of England, never goes abroad - Standing & running rigging all new

If Sheathed, Doubled, Felted, or Coppered _____ When last done _____


I am of opinion this Vessel should be Classed _____

The Amount of the Fee.....£ : 10 : is received by me, M. Deveney Surveyor
 Special£ : :

Committee's Minute 28th Jan'y 1842

Character assigned Sound to A + 1

received repairs



Deponed
 And the Surveyor at Milford who he knows and says of them repairs being the new but repairs
