

No. 76 Survey held at Weyford Date October 3rd 1842
 on the Schooner Nulda Master Capt. King
 Tonnage 76 Built at Topsham in Devon When built in the year of 1825
 By whom built Owners Messrs Roach & Jeffers
 Port belonging to Weyford Destined Voyage Glasgow
 If Surveyed Afloat or in Dry Dock afloat See Weyford No 20 Classed ship mounted

Length aloft	Feet. Inches.	Extreme Breadth	Feet. Inches.	Depth of Hold	Feet. Inches.
	58		16		10
Scantlings of Timber.				Thickness of Plank.	
Timber and Space	each	Inches.	Inches. Middle	Outside.	Inches. Inside.
Floors	sided	9	10	Keel to Bilge	Foot Waling
1 st Foothooks	"	10	" 10	Bilge Planks	Bilge Planks
2 nd Ditto	"	10	" "	Bilge to Wales	Ceiling in Flat
3 rd Ditto	"	-	" -	Wales	Ditto Bilge to Clamp
Top Timbers	"	6	" 6 5	Topsides	Hold Beam Clamps
Deck Beams ... N°. of 10	"	9	" 10	Sheer Strakes	Deck Beam Ditto
Hold Beams ... N°. of -	"	-	" -	Plank Sheers	Ceiling 'twixt Decks
Keel	"	-	" -	Water-Ways	Hold Beam Shelfs
Kelsons	"	21	" 13	Upper Deck	Deck Beam Ditto

Size of Bolts in Fastenings.	Iron.
Heel-Knee, and Dead Wood abaft	Hold Beam
Scarps of Keel	Deck Beam
Floor Timber Bolts	3/4
Kelson ditto	-
Transoms and throats of Hooks	same in Iron above the Copper
Arms of Hooks	{

Timbering.—The Space between the Floor Timbers and Lower Foothooks in this Vessel is 2 Inches. The Space between the Top-timbers is 3 Inches. The Stem, Stern Post, are composed of English oak the Transoms, Aprons, Knight Heads, Hawse Timbers, of English oak and are quite free from all defects. The Floors and first Foothooks are composed of English oak Timber. The other Foothooks and Top Timbers of English oak. The Shifts of the first and second Foothooks are not less than N. B. When less than prescribed by the Rule, state how many. The rest of the Shifts of the Frame are . The Frame is well squared from the first Foothook Heads upwards, and free from sap, and from thence downwards, the frame is well.

The alternate Frames are bolted together. N. B. If not, state how bolted. The Butts of the Timbers are close together; their thickness not less than of the entire moulding at that place. The Frame is chocked with Butt at each end of the chock. The Main Kelson is composed of English oak and the False Kelson of Mercurial. The Scarps of the Kelsons are not less than 5 feet inches. The Scarps The Deck and Hold Beams are composed of Deck beams of the best English oak.

Planking Outside.—From the Keel to the first Foothook Heads the Plank is composed of English Elm. From the first Foothook Heads to the Light Water Mark of English Elm. From the Light Water Mark to the Wales of English oak. The Wales and Black-strokes are of English oak. The Topsides of English oak. The Sheer-strokes and Plank-sheers of English oak. The Water-ways of English oak. The Decks of Mercurial planed State of In a very good state. The Shifts of the Planking are not less than 5 Feet Inches. N. B. If less than prescribed by the Rule, state whether general or partial, and if partial, in what part of the Ship. Generally The Planking is wrought between

Planking Inside.—The Limber-strokes are composed of English oak the Bilge Planks of English oak. The Ceiling, Lower Hold, of English oak Between Decks of English oak. Shelf Pieces of English oak Clamps of English oak.

Fastenings.—To Hold Beams Four pieces to each beam were fastened & secured. Deck Beams

Number of Breasthooks Three Pointers Crutches

Butts End Bolts are of half inch in the Bottom, and one Bolt in each Butt End through and clenched.


Bilge and Footwaling $\frac{7}{8}$ bolted through and clenched. in side all sail

General Quality of Workmanship of the best description

We certify that the preceding is a correct description of the above-named Vessel.

Builder's Name _____

Surveyor's Name M. D. Deane



Her Masts, Yards, &c. are in good condition, and sufficient in size and length.

She has SAILS.

CABLES, &c.

ANCHORS, and their weights.

N°.	Fathoms.	Inches.	N°.	
2	Fore Sails,	140	Chain	2
2	Fore Top Sails,	70	Hempen Stream Cable	1
1	Fore Topmast Stay Sails,	-	Hawser	1
2	Main Sails,	70	Towlines	2
	Main Top Sails,	70	Warp	2 1/2
	and is well found in other Sails — being good		All of quality.	

Her Standing and Running Rigging very good sufficient in size and good in quality.

She has one good boat Long Boat and _____

The present state of the Windlass is good Capstan _____ and Rudder good —

General Remarks—Statement and Date of Repairs.

This vessel has just come from Melford after getting a good repair, such as new top timbers & coaming boards, waterways & all new stanchions fore & aft & new bulwarks & some shifts of planks in decks. likewise new channel blocks are all bolted to the deck knees, some new knees to decks were bolted waterways 4 inches thick, stern frame nearly all new with new planks, nearly all newly bent bolted all over & likewise all the timbers that was required & has been caulked all over, decks & deck frame & all parts of this vessel is in the highest state of repair & is fit to carry a cargo of dry & perishable goods to any part of the world. I would consider this ^{vessel} as good as any first class vessel in this port for four or five years.

Provided she is kept in good repair.

If Sheathed, Doubled, Felted, or Coppered _____ When last done _____

I am of opinion this Vessel should be Classed 11 4 years —

The Amount of the Fee.....£ : 10 : 0 is received by me,

A. Deacon Surveyor

Special£ : :

Committee's Minute 18th October 1843

Character assigned _____

[Signature]

E. J. L.D.



© 2021

Lloyd's Register
Foundation