

No. 331 - Survey held at Norfolk Date 1<sup>st</sup> September 1859  
on the Shooner "Rockford" Master J Carroll 331  
Tonnage Old      New 50 Built at Albany When built 1838 Launched       
By whom built      Owners Mr Rockford  
Port belonging to Norfolk Destined Voyage Gloester  
If Surveyed while Building, Afloat, or in Dry Dock On Plant Ship

Length aloft .....	Feet.	Inches.	Extreme Breadth Outside .....	Feet.	Inches.	Depth of Hold .....	Feet.	Inches.
<b>Scantlings of Timber.</b>								
TIMBER AND SPACE .....		Inches.		Inches.	Inches.	<b>Thickness of Plank.</b>		
Floors .....	sided	12 1/2	—	Moulded	8 1/2	<b>Outside.</b>		
1 <sup>st</sup> Foothooks .....	"	1 1/2	"	"	7 1/2	Garboard Strakes .....	2 1/2	<b>Inside.</b>
2 <sup>nd</sup> Ditto .....	"	1 1/2	"	"	6	Garboard to Bilge .....	2 1/2	Limber Strakes .....
3 <sup>rd</sup> Ditto .....	"	1 1/2	"	"	5	Bilge Planks .....	3 1/2	Bilge Planks .....
Top Timbers .....	"	6 1/2	"	"	4	Bilge to Wales .....	2 1/2	Ceiling in Flat .....
Deck Beams N <sup>o</sup> 1 } Average Space } 2 ft 6 in	"	8	"	"	6	Wales .....	3	Ditto Bilge to Clamp ....
Deck Beams, length amidships .....	"	—	"	"	—	Topsides .....	3	Hold Beam Clamps .....
Hold Beams N <sup>o</sup> 1 } Average Space }	"	—	"	"	—	Sheer Strakes .....	3	Deck Beam Ditto .....
Hold Beams, length amidships .....	"	—	"	"	—	Plank Sheers .....	3	Ceiling 'twixt Decks ....
Keel .....	"	8 1/2	"	"	8 1/2	Water-Ways { Upper Deck	2 1/2	Hold Beam Shelves .....
Scarphs of Ditto .....	"	8 1/2	"	"	8 1/2	Lower Deck	1 1/2	Deck Beam Ditto .....
Keelsons .....	"	8 1/2	"	"	8 1/2	Upper Deck .....	5 inches oak	—
Scarphs of Ditto .....	"	—	"	"	—			—

Size of Bolts in Fastenings, distinguishing whether Copper or Iron; also of Treenails.

	Copper Inches.	Iron Inches.		Copper Inches.	Iron Inches.		Copper Inches.	Iron Inches.
Heel-Knee, and Deadwood abaft			Transoms and throats of Hooks			Hold Beam Bolts in		
Scarphs of Keel.....N <sup>o</sup> 1			Arms of Hooks			Waterway ..		
Keelson Bolts through Keel at each Floor	1	1	Bolts thro' Bilge & Limber Strakes, or Thickstuff over Double Floors	3/4		Knees .....		
Bolts through Heels of Timbers against Deadwood			Butt End Bolts	1/2		Shelf or Clamp		
			Pintles of the Rudder	2		Waterway ..		
						Knees .....		
						Shelf or Clamp		
						Nails or Bolts in Flat of Deck		
						Treenails .....		

**Timbering.**—The Space between the Floor Timbers and Lower Foothooks is 4 Inches. The Space between the Top-Timbers is 4 Inches.  
The Floors consist of French Oak The First Foothooks of French Oak Timber.  
The Second Foothooks of      The Third Foothooks and Top Timbers of French Oak  
The Shifts of the First and Second Foothooks are not less than      N. B. When less than prescribed by the Rule, state how many.  
The rest of the Shifts of the Frame are       
The Frame is well squared from the First Foothook Heads upwards, and free free from sap, and from thence downwards, the frame is as per rule

The alternate Frames are all bolted together to the Gunwale. N. B. If not, state how bolted.  
The Butts of the Timbers are      close together; their thickness not less than      of the entire moulding at that place.  
The Frame is      choaked with      Butt at each end of the choek. The Main Keel is French Oak  
The Main Keelson is French Oak and is free from all defects. The False Keelson is       
The Stem, and Stern Post, consist of French Oak The Transoms, Aprons, Knight Heads, and  
Hawse Timbers of French Oak Deadwood, of      and are      free from all defects.  
The Deck and Hold Beams consist of French Oak The Breasthooks of Oak The Knees of Oak

**Planking Outside.**—From the Keel to the Height defined in Note to Table A } the Plank is French Oak  
or to the First Foothook Heads }  
From the above named Height to the Light Water Mark French Oak  
From the Light Water Mark to the Wales French Oak  
The Wales and Black-strakes are French Oak The Topsides French Oak  
The Sheer-strakes and Plank-sheers French Oak The Water-ways { Upper Deck French Oak  
Lower Deck       
The Decks French Oak & pine State of new  
The Shifts of the Planking are not less than 4 Feet      Inches. N. B. If less than prescribed by the Rule, state whether general or partial, and if partial, in what part of the Ship. The Planking is wrought      between, and without step-butting.

**Planking Inside.**—The Limber-strakes and Bilge-strakes are French Oak  
The Ceiling, Lower Hold, and between Decks French Oak Shelf Pieces and Clamps French Oak  
**Fastenings.**—To Hold Beams     

Deck Beams Four good oak      each beam well bolted & secured  
Number of Breasthooks Three Pointers      Crutches       
Butts End Bolts are of Iron in the Bottom, and One Bolt in each Butt End through and clenched.  
Bilge and Limber Strakes all bolted through and clenched. Treenails of Principles How Made Turned  
Thickstuff over Double Floors      bolted through and clenched. General Quality of Workmanship very good  
We certify that the above is a correct description of the several particulars therein given  
Builder's Signature      Surveyor's Signature M. J. G. G. G.



Her Masts, Yards, &c. are in new condition, and sufficient in size and length.

She has SAILS.		CABLES, &c.		ANCHORS, and their weights.	
N <sup>o</sup> .			Fathoms. Inches.	N <sup>o</sup> .	Weight.
2	Fore Sails,	Chain .....	125 7/8	2	5-0-0
1	Fore Top Sails,	Hempen Stream Cable .....	75 3	1	6-0-6
1	Fore Topmast Stay Sails,	Hawser .....	- - -	1	1-3-0
1	Main Sails,	Towlines .....	45 3	1	1-0-0
1	Main Top Sails,	Warp .....	75 2		
and <u>some spare sails</u>		All of <u>good</u> quality.			

Her Standing and Running Rigging Complete sufficient in size and good in quality.

She has one good Long Boat and fully Equipped

The present state of the Windlass is good Capstan touch Rudder new Pumps good

### General Remarks and Statement and Date of Repairs, if any.

DATES of Surveys held while building, as per Section 35.	1st.	When the Frame is completed	
	2nd.	When the Beams are put in, &c.	
	3rd.	{ When completed, and before the plank be painted or payed }	

*This vessel has been stranded on this last - last winter, and sold by auction to the present owner, received very little damage, one side of her, been much shraped, which has been taken out & made all new. - she is a very strong vessel and built of very good material, & through, the only fault is that shift of plank are short.*

Present condition of Caulking of Bottom, good Deck, good and Waterways very good

If Sheathed, Doubled, Felted, or Coppered - - - - - When last done - - - - -

I am of opinion this Vessel should be Classed A' For Six years

The Amount of the Fee.....£ 1 : 0 : 0 is received by me, Mr. Devereux

Special .....£ : :

Certificate ....£ : 2 : 6

Committee's Minute 6<sup>th</sup> September 1859

Character assigned 1 for 12 years



© 2021

Lloyd's Register

Foundation

59