

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 22nd OCT. 1938. When handed in at Local Office 24. 10. 38 Port of GLASGOW.No. in Survey held at GLASGOW. Date, First Survey 20th OCT. Last Survey 21st OCT. 1938.
Reg. Book. (No. of Visits 2)52073 on the ~~Wood, Iron or Steel~~ 4 Mst. Bk. OLIVEBANKTONNAGE: Built at GLASGOW. By whom MACKIE & THOMSON. When 1892 10
GROSS 2795 Owners REDERI A/B OLIVEBANK Owners' Address AS RECORDED.
UNDER DK. 2639 (G. ERIKSON) (if not already recorded in Appendix to Register Book).
NET 2427 Managers Port belonging to MARIEHAMN.

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock GORAN N°2. Destined Voyage AUSTRALIA.

WB=Cell DBor DBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 60278 Port GLS.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR DOCKING.

NOW DONE: Vessel placed in dry dock, bottom & rudder cleaned, examined, found satisfactory & re-coated.
Decks, deckhouses, hatch coamings, ventilators, etc examined & found satisfactory.
N°1 hold generally examined & found satisfactory.
Freeboard rough checked.

REPAIRS-WEAR-TEAR- a few minor deck repairs effected.

STEERING GEAR SPARES:— There are no spares for the hand steering gear, on board.

SUMMARY OF DAMAGE REPAIRS:—

	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Decks (wood) good	State if Tanks have been examined inside no	Air and Sounding Pipes not examined	Copper, or Y.M. of Wood Vessels (State if on Felt) ✓
Caulking of Decks "	State if Tanks now tested no	Dblng. Plates under Sounding Pipes "	When put on, Month Year ✓
Coamings "	Bulkheads good in spaces examined	Engine Room Skylights good ✓	Boats not examined
Beams & Fastenings good in spaces examined	Ceiling " " " "	Coal Bunkers, Open'gs, Lids, &c. ✓	Masts, Yards, &c. good ✓
Outside Plating good	Cement on Asphalt not examined	Oil Bunkers ✓	Condition, how ascertained from deck
" " in way of sidelights not examined	Rudder good	Scuppers ✓	(State if wedges removed) no
Breasthooks " "	Steering gear and its connections "	Cargo Hatchways good ✓	Sails not examined
Transoms " "	Windlass "	Hatches " "	Equipment letter X
Frames good in spaces examined	Have pumps now been examined and found efficient? not examined	Blanking of Wood Vessels	Anchors, No. of 3-1-1 ✓
Reverse Frames " " " "	Have Sluice Valves now been examined and found efficient? not examined	Caulking ditto	Chain Locker not examined
Longitudinals ✓	Have Watertight Doors now been examined and found efficient? not examined	Treenails ditto	Cables (State if now ranged) no
Transverses ✓	Have Ventilators and their Coamings been examined and found efficient? yes	Breasthooks & Stemson ditto	" length (on board) mean diam. ✓
Floors not examined		Transoms Pointers, & Crutches ditto	" Rule length size ✓
Keelsons " "		Timbers of Frame at openings ditto	Hawser & Warps sufficient
Stringers good in spaces examined		Ditto Ditto at other places ditto	Standing and Running Rigging good
Inner Bottom Plating ✓		Stringers, Clamps & Shelves ditto	
		Selling (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel, so far as now seen, is in an efficient condition, & eligible in my opinion to remain as at present classed in the Register Book, with fresh record of survey 10, 38.

Survey Fee (per Section 29) £ : : Fees applied for, 19
Special Damage or Repair Fee (if any) (per Sec. 29) £ : : Received by me, 19
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :

Geo Cockburn

Surveyor to Lloyd's Register of Shipping.

Committee's Minute GLASGOW 25 OCT 1938

Character Assigned 100A1
10.38

© 2021

Lloyd's Register Foundation