London 69

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Port CALCUTTA

24th July, 1958.

This is to Certify that

E.D.COOK.

the undersigned Surveyor to this Society did at the request of

Owners Superintendent survey the S.S."JALAGANGA" 4981 tons gross
ombay on the 12th July, 1958 and subsequently whilst the ship was
at at Calcutta for the purpose of ascertaining the nature and
nt of contact damage stated to have been caused by a lighter on
1st June 1958 at Bedi Bunder.

For further particulars see Log Books.

The undersigned upon examination

FOUND	RECOMMENDED
1 plate H2 (port side aft) ced at one place and fitted a bolted patch.	Remove patch, crop plate and fit spigot patch by welding.
1 plate H2 (port side aft) ly set in at one place.	Crop plate, fit spigot patch by welding.

Repairs to be tested as necessary on completion.
New and disturbed work to be recoated as necessary.

bove recommendations have been made in order to place the ship
good a condition as she was in before the alleged casualty, and
been carried out to my satisfaction.

E. D. Cook.

SURVEYOR TO LLOYDS REGISTER OF SHIPPING
UNITED WITH THE BRITISH CORPORATION REGISTER

m. Rpt - 50/-
- 8/-

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society
perly executed, it is to be understood that neither the Society nor any Member of any of its Committees is
any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by
ociety or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any
of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or
Officers or Agents of the Society."

© 2021 Lloyd's Register Foundation

003013-003017-0026