REPAIRS, OR EXAMINATION AS PER RULE, FOR DAMAGE ETC.

ACTION is DEFERRED for examination in dry dock after grounding.

o Chief Surveyors ..... *Received from Chief Surveyors* .....

SEL'S NAME "THAUMASTUS" *REPORT* Liv. *No.* 128939

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(*Extract from Sub-Committee's Report*, 24/5/92.).

of Survey DOCKING, DAMAGES & EQUIPMENT *~~When due~~* (S.R.L.)

NOTED.

ENDORSEMENT OF CLASS (B).

Indents in shell plating in way of O.F. bunker (s.s.)

Delete from SRL
Dry docking (grounding)

W.O.T.
30.6.49.

© 2020 Lloyd's Register Foundation

003046-003055-0117

his survey, thus, for example :—" ..... to remain as classed in the Register Book *without fresh record of Survey*," " to remain as classed
urvey, 1.38." or " to remain as classed and to have record of survey, 1.38 and the notations of