C O P Y

~~CONFIRMATION~~ OF LETTER.

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.

23rd April, 1918.

Dear Sirs,

With reference to Mr.Dippie's First Entry Report No.10082 on the new Steamer "RONA", I have to request that you will be good enough to state whether the whole of the requirements of the Specification for carrying oil fuel in the double bottom have been complied with, and whether, in your opinion, a notation to this effect should be made in the Register Book.

It is concluded that the stringer plates at the base of the topside tank are 42" in breadth as shown on the approved plan, and not 36" as stated, but you should state if this is so.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,

MIDDLESBROUGH.

© 2021 Lloyd's Register Foundation

003534-003540-0232