RECEIVED
- 2 MAR 1951
Ansd.

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Reference

201, Tower Building, Liverpool, 3

Telegrams: Register, Liverpool

1st March, 1951.

Telephone: Central 8891 (5 Lines)

Dear Sir,

With reference to Liverpool F.E. Report No.132467 on Messrs. Cammell Laird & Co's Yard No.1203, S.S."GENERAL SAN MARTIN", it is regretted that the Electrical fee is incorrect and should read £114:10:0d. allocated as follows:-

a/c Liverpool.	£91:	15:	0d.
a/c London.	£11:	7:	6d.
a/c Sunderland.	£11:	7:	6d.

An amended account has been sent to the Builders and the balance of fee entered in the Debit and Rough Fee Books, and I shall be obliged if you will kindly make the necessary alteration on the report in question.

Yours faithfully,

Secretary to the
Liverpool Committee.

The Secretary,
LONDON.

© 2021 Lloyd's Register Foundation

008786-008788-0089

line below Are they each fitted with a Discharge Valve always accessible on the plating of the vessel yes Are the Blow Off covering plate yes What pipes pass through the bunkers none How are they protected

CLASSIFICATION
S
ACCOUNTS

© 2021
Lloyd's Register
Foundation