COPY.

32431

Rpt. C 12(b).

FREEBOARD VERIFICATION FORM FOR STEAMERS CARRYING TIMBER DECK CARGOES.

When received in London Office ___ **-4 NOV 1932**

Port *New Orleans, La.*

Name *"Vestvangen"*

Official No. _____ No. in Reg. Book *73996.*

Port of Registry (*For Foreign Ships*) *Oslo*

Iron or Steel *Steel* State whether Classed by Lloyd's Register *Yes.*

Name of Owners *Skibs. A/S Karaibien* Date of Verification *Oct. 20th 1932.*

I have to report that the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:—

ORDINARY CARGO ~~AND~~ ~~PASSENGER~~ SHIPS.

Freeboard amidships from top of deck line, ~~wood~~/steel deck.   From centre of disc.

	ft.		ins.		
Tropical Fresh Water	1	11	ins.	9¼	ins. above
Fresh Water	2	3½	ins.	4¾	ins. above
Tropical	2	3¾	ins.	4½	ins. above
Summer	2	8¼	ins.		
Winter	3	0¾	ins.	4½	ins. below
Winter North Atlantic	3	2¾	ins.	6½	ins. below

SHIPS CARRYING TIMBER DECK CARGOES.

Freeboard amidships from top of deck line, ~~wood~~/steel deck.   From centre of disc.

	ft.		ins.		
Tropical Fresh Water Timber		11	ins.	21¼	ins. above
Fresh Water Timber	1	3¾	ins.	16½	ins. above
Tropical Timber	1	4¾	ins.	16¼	ins. above
Summer Timber	1	8¼	ins.	11½	ins. above
Winter Timber	2	3	ins.	5¼	ins. { above ~~below~~
Winter North Atlantic Timber	3	2¾	ins.	6½	ins. below

Maximum Summer Draught corresponding to the freeboard assigned as shown on the Builders' Displacement Scales:— *17'-11½"*

_____ Surveyor.

(*To be filled up in London Office.*)

Statement No. _____ Date of Committee's Minute _____

Particulars for Record in Register Book. { Moulded Depth . . . _____ ft. _____ ins.
Freeboard . . . . . _____ ft. _____ ins.
Corresponding Draught _____ ft. _____ ins.

Freeboards compared and found correct by _____ Date _____

Is fee paid? _____ Form for Certificate _____

Instructions _____ Date _____

Certificate written _____ Noted for posting _____

For particulars form see markings from Oslo 11/11/32

4m.7.31.

008909-008916-0225

be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other