Received from Chief Ship Surveyor 20 FEB 1962

SHIP'S NAME "MARINE TRAVELLER" REPORT YAK. No. 4008

EA

nding Conditions of Class: SUBJECT to leaky F.P. bulkhead and deep tank E.R. bulkhead etc. (p.s) being dealt with, also to Nos.7 & 8 shell plates in 4th strake below sheerstrake and adjacent strake (p.s.f) and to rudder stock and steady bearing being specially examined and dealt with as necessary by the Special Survey.

ACTION is DEFERRED for Special Survey.

Appendix. (As before ~~or None~~)

s due: SPECIAL SURVEY (C) became due 1,61 but postponement until 1,62 was approved 18.9.61.

of Present Survey: (Afloat ~~and in dry dock~~)

Deferred repairs on account of collision damage.

l Features:

erim Certificate in order (Yes-~~No-None~~)

Outstanding: (If any for S.S.)

ALL ITEMS.

to be completed by:

mendation: SUBJECT as above and to sheerstrake plating (aft) being examined and dealt with as necessary at the next drydocking, but further ACTION continue to be DEFERRED for Special Survey.

SUBJECT.

IN S.R.L.APPENDIX.
'A' strake (p & s) also upper deck stiffened with minor corrugations in way unfaired.

OFFICE NOTE.
Bottom plating partially stiffened.

W.O.T.
20/2/62

Rm 3-16/2 Not u/s Yka
" " " Note
" " " Sale

Ak (new)

© 2021 Lloyd's Register Foundation

010484-010494-0213