Boilers made at Glasgow By whom made A Hilton Sons Ltd. Boiler No. 538

pt. 7. For the information of Surveyors and the Committee only.

Received at ..... Office, ... 19

Lloyd's Register of Shipping.

(Report on Machinery, No. ~~54392~~ Port Glasgow)
Westaki

No. ..... ENGINE FORGINGS ~~OR CASTINGS~~.

I have to report that the Forgings ~~or Castings~~, as herein described, manufactured by Messrs T. S. Foster & Son Ltd *of* Sunderland *for the Engines No.* 538 *being constructed by* Messrs Stephens & Son Ltd. *of* Glasgow *for the Ship No.* ....., *being built by* ..... *of* ..... *have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects. These have been despatched to* .....

on Forgings ~~or Castings~~.

Lloyd's
No. 7031A
GD 20·10·33

J Dale
Sunderland

Replace Piston Rod

	CRANK SHAFT. FLYWHEEL SHAFT.	~~THRUST SHAFT.~~	INTERMEDIATE SHAFT.	TUBE SHAFT. SCREW SHAFT.
erial*		S Jn Ingot-Steel		
made		Forged		
nnealed		yes		
ensions, Forgings				
ght, Castings ...				
gress on Inspection ...		Forging & Testing		
sts on Standard Test Pieces.				
sile Test— ons per square inch ...		30·4		
xtension per cent ...		32%		
Bending Test— ngle before fracture ...		180°		
es when Inspected		19-20/10/33		

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:—

LLOYD'S REGISTER OF SHIPPING 23 OCT 1933 GLASGOW

ee (if any chargeable) £ ..... To be paid at .....

* If of wrought iron, state whether piled bars or scrap. If of steel, state whether made by the Open Hearth process.

n,8,26.

© 2020 Lloyd's Register Foundation

011079-011088-0070