COPY.

Lloyd's Register of Shipping.

Port Portland, Oregon

30th January 1949.

9371

This is to Certify *that* we *have Surveyed the* Donkey *Boiler and Machinery of the* Single Screw Motor Vessel "NELLY" ex "Long Island" ex "Mormacmail" 7886 tons gross of Panama whilst afloat and in drydock at Portland, Oregon on the occasion of the vessel being presented for Classification with Lloyd's Register of Shipping *and that* we *have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by* us *in connection therewith have been carried out to* our *satisfaction, and that* we *have* **Recommended** *that the* ~~record of~~ machinery ~~of the vessel~~ be favourably considered by the Committee for Classification with Lloyd's Register of Shipping and may then be entitled to records of L.M.C. (C.S.) 1,49 T.S.(C.L.) 1,49 and D.B.S. 1,49 ~~be made~~ *in the Register Book* ~~in the case of this vessel when the survey has been completed~~ subject to spare propeller being supplied at the earliest opportunity

Parts now examined:—

Port and Starboard forward and aft main engines, inboard and outboard forward also aft auxiliary Diesel generators and all auxiliary machinery, main thrust, thrust shaft, intermediate shafting and all bearings, vessel's pumping arrangements, oil fuel tanks, electrical installations, steam pipes and air receivers, steering gear and windlass.

(Signed) JAMES F. ROBERTSON, E. MARLBOROUGH

Engineer Surveyors to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

B1. (C.S.) 10M-11-42 PRINTED IN U.S.A.

© 2021 Lloyd's Register Foundation

012796-012800-0052