COPY Original & 1 copy, handed to Campero London.

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Port CADIZ

23rd. January 1962

**This is to Certify** that I have surveyed the Boiler and Machinery of the M.T. "CAMPERO", 6382 tons gross of Malaga, in dry dock and afloat at Empresa Nacional "Bazan", La Carraca, Cadiz, on the 7th. December 1961 and on subsequent dates, for advancement of Continuous Survey of Machinery, Docking Survey and Auxiliary Boiler Survey

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have **Recommended** that the record of CS. with date

be made in the Register Book in the case of this vessel when the survey has been completed, subject to all furnaces of Auxiliary boilers being renewed before the end of July 1962, the boiler pressure not to exceed 8 kg/cm² in the meantime.

Parts now examined:—

Port Main Engine:- All connecting rods, top ends and guides.
All crankpins and bearings.
All journals and bearings.
Blast injection compressor.

Stbd.Main Engine:- Nos. 3 & 4 Cylinders, Pistons, Rods, Valves & Gears.
All connecting rods, top ends and guides.
All crankpins and bearings.
All journals and bearings.
Blast injection compressor.

Port and Stbd. Auxiliary Engines and blast injection compressors.
Independent circulating pump.

Surveyor to Lloyd's Register.
Signed: J.Douglas.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or ation of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or rs, or other Officers or Agents of the Society."

Certificate has been issued in the Spanish language en the reverse side of the original.

(S.). R. 4 (Copia).

© 2021 Lloyd's Register Foundation

013671-013677-0054