Continuation / 4451

REPORT of SURVEY for REPAIRS.

No. 544 Survey held at London Date July 3rd 1848

on the Bk Spartan Master Barclay

Tonnage 269 72 Built at Gainock When built 1839

By whom built — Owners Thomson

Port belonging to London Destined Voyage Jamaica

If Surveyed Afloat or in Dry Dock Kings Dock

Last Survey, No. 13761 Port London Classed A. 1

REPAIRS Present Time Many New Timbers (100) New bolts in upper deck Knees, Shipped Caulked from the Keel up. and Sheathed with yellow Metal a New Pair of long iron Stocks fitted to Knee of Head

Surveyed Bright from the Lower part of the bilge up and Surveyed as required by Society's Rules Section 34

The upper deck, the Coamings the bolts of the Knees of both decks the whole of the outside planking from the Keel up the plank Sheers Waterways Beams Hanse timbers Keelson Heads, Breast Hooks transoms the floors & Kelsons, the Ceiling the frame and inner Surface of the outside plank all in good Condition the Keel is Straight and the Sheer and general form of the Ship unaltered

Present Condition of the

Decks		Treenails	Windlass and Capstan effectual
Waterways		Breasthooks and Stemson	Pumps do
Comings		Transoms, Pointers, and Crutches	Boats do
Upper Deck Beams & Fastenings	Good	Timbers of the Frame	Masts, Yards, &c. do
Lower Deck Beams & Fastenings		Keelsons Good	Sails do
Planksheers Sound		Clamps and Shelfs	Anchors No. of 3 4 3 1 1 do
Sheerstrakes Sound		Ceiling	Cables do
Topsides Do		Rudder	Hawsers and Warps do
Wales Do		Copper Yellow Metal When put on 1848	Standing & Running Rigging do
Plank (Bottom) and Counter		on feet about 7 feet below	

General Observations and Opinion,

Is now in effectual Condition and Eligible to be continued 3 years A1 from 1847—

Thomson

The Amount of Fee.....£ 3 : — : — is received by me

Special..... 3 : 3 : —

Certificate (if required) — : — : —

Committee's Minute 25th July 1848

Character assigned A1 for 3 Years

Thomson & Co

© 2019 Lloyd's Register Foundation
LON 625-0132