Rpt. 8. ARCHON (Recei... No.

REPORT of SURVEY for REPAIRS,

DISCLASSED BOX No. 98 (Boston)

Date of writing Report 29th Dec. 1930 When handed in at Local Office 29th ... 1930 Port of NEW YORK DISCLASSED BOX No. 9...

Reg. Book. Survey held at --- Date, First Survey --- Last Survey (No. of Visits)

64761 on the ~~Wood~~ ~~Iron~~ ~~or~~ Steel Sc. S. "ATLANTIC" N/N ARCHON 92B

TONNAGE:— Built at San Pedro, Cal. By whom South Western S.B. Co. When 1919 YEAR.

GROSS 5521

UNDER DK. 5058

NET 3455

Owners Argonaut S. S. Line Inc. Owners' Address 26 Beaver Street, N. (if not already recorded in Appendix to Register Book).

Managers ~~After SS Co~~ Port belonging to New York

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet

total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any)
✠100 Al 9-30		L.M.C. 2-27
S.S.N.Yk.No.2-27		B.S. 5-30
		C.L.N 9-30
Fitted for oil fuel above 150°F.		10,23 F.P.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 4910 Port BOS

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

...es where the Surveyor has not made a special damage report he is required to state whether he ...ervices for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified ... ft. ... ins.

Was a damage report made by anyone else? If so, by whom?

...XAMINATION AS PER RULE, FOR

The Owners have requested that this vessel be withdrawn from classification with ...ety (see copy of letter from the Owners' dated December 22nd, 1930)

Mr J. F...nch
Lloyd's ...gi...
1... Battery Place,
New York City.

Dear Sir:-

In connect... to the SS. "HENRY S. G... Lloyd's Regi...ter of Shi... $590.00, also bill from ... in the amount of $600. ... the SS. "CHARLES H. ... $1200.00 by each ... expense as a res... to withdraw abo... instant.

...In vi... it is with consi... necessary to tak... S... ...th si... ...ks ...al ...

Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—

Transoms

Frames

Reverse Frames

Longitudinals

Transverses

Floors

Keelsons

Stringers

Inner Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt (State which.)

Rudder

Steering gear and its connections

Windlass

Have Pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Dblng. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking ditto

Treenails ditto

Breasthooks & Stemson ditto

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shelfs ditto

Salting (State if examined.) ditto

Copper, or Y.M. of Wood Vessels (State if on Felt).
When put on, Month Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

,, length (on board) size

,, Rule length size

Hawser & Warps

Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey. 1,24," or "to remain as classed and to have record of survey, 1.24, and the notations of *ss No.* 1-24 and ptND24, &c."

Survey Fee (per Section 29) £ :

Special Damage or Repair Fee (if any) (per Sec. 29) £ : :

Travelling Expenses (if chargeable) £ : :

Second Surveyor's Fee (if any) £ : :

Fees applied for, ... 19...

Received by me. ... 19...

John S. Heck
Surveyor to Lloyd's Register of Shipping.

NEW YORK DEC 30 1930

Committee's Minute

Character Assigned Withdraw class and insert (..) Decision of Classing Committee
Lr Nyk 15/1/31 confirmed

General Committee
Thursday, 15th January, 1931.

10m.7.29.—Transfer Ink.
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

If Certificate required? If so, to be sent to

W252 - 0142

© 2012 Lloyd's Register Foundation