Rpt. 8.

(Received at London Office .....)

DISCLAIMER BOX NO. 4 Tyne

No. 11225

REPORT of SURVEY for REPAIRS, &c.

RETAIN

Date of writing Report March 4th 1922 When handed in at Local Office March 4th 1922 Port of Middlesbrough

No. in Reg. Book. 23580 Survey held at Tyne on the ~~Wood, Iron or~~ Steel S.S. "Margha" Master

Date, First Survey ..... (No. of Visits 1) Last Survey March 3rd 1922.

TONNAGE:—
GROSS 8258
UNDER DK. 6821
NET 5091

Built at Glasgow By whom Barclay Curle & Co Ltd When 1917 (YEAR.) 12 (MONTH.)

Owners British India Stm Nav Co Ltd Port belonging to Glasgow.

Owners' Address .....
(If not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Smiths Destined Voyage Ile East.

WB=CellDBorDBa ..... feet; uE&B ..... feet; f ..... feet;
total capacity ..... tons. FPT ..... tons; APT ..... tons; MT ..... feet ..... tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 11116 Port Hull

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now Expired.	Machinery and Boiler Surveys (including date of N.B., if any).
✠ 100 A.1. 1921		✠ L.M.C. 12.7

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified ..... ft. ..... ins.

In ~~Classed~~ cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

Now done:- Vessel placed in dry dock, bottom mudder examined, cleaned & coated, Deck, Steering Gear & connections, ventilators & general equipment examined. Cables ranged & examined.

Attention was drawn to the Special Survey 8th now due, but owners representative stated that this will not be carried out.

28 - Glasgow
Cert 1922

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks Good
Caulking of Decks .
Waterways .
Coamings .
Beams & Fastenings .
Outside Plating Good
Caulking of ditto .
Rivets .
Breasthooks & Crutches ✓
Transoms ✓
Frames ✓
Reverse Frames ✓
Floors ✓
Keelsons ✓
Stringers ✓
Inner Bottom Plating ✓

State if Tanks have been examined inside no
State if Tanks now tested no
Bulkheads ✓
Ceiling ✓
Cement or Asphalt (State which.)
Rudder Good
Steering gear and its connections .
Windlass .
Have Pumps now been examined and found efficient? ✓
Have Sluice Valves now been examined and found efficient? ✓
Have Watertight Doors now been examined and found efficient? ✓
Have Ventilators and their Coamings been examined and found efficient? Yes

Dblng. Plates under Sounding Pipes ✓
Engine Room Skylights Good
Coal Bunkers, Open'gs, Lids, &c. .
Scuppers .
Cargo Hatchways .
Hatches .
Planking of Wood Vessels ✓
Caulking ditto ✓
Treenails ditto ✓
Breasthooks & Stemson ditto ✓
Transoms, Pointers, & Crutches ditto ✓
Timbers of Frame at openings ditto ✓
Ditto ditto at other places ditto ✓
Stringers, Clamps & Shelfs ditto ✓
Salting ditto ✓
(State if examined.)

Copper, or Y.M. of Wood Vessels ✓
(State if on Felt.)
When put on, Month ✓ Year
Boats Good
Masts, Yards, &c. .
Condition, how ascertained from deck
(State if wedges removed) ✓
Sails ✓
Equipment letter C
Anchors, No. o 3 B 1 S 1 K
Cables (State if now ranged) Yes
„ length 300 size 2 3/4
(on board)
„ Rule length 300 size 2 3/4
Hawser & Warps Good
Standing & Running Rigging .

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent? (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Is Certificate required? If so, to be sent to

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of *ss No.* 1–15 and ptND15, &c."

This vessel is now in good and efficient condition and eligible in my opinion to remain as classed, without fresh record of Survey.

Survey Fee (per Section 28) ..... £ : :
Special Damage or Repair Fee (if any) (per Sec. 29) ..... £ : :
Travelling Expenses (if chargeable) ..... £ : :
Second Surveyor's Fee (if any) ..... £ : :

Fees applied for, ... 19 .....
Received by me, ... 19 .....

4+2

W. A. Brydon.
Surveyor to Lloyd's Register of Shipping.

Committee's Minute TUE. MAR. 14 1922

Character Assigned Omit class on reprint of Reg. Bk JMcH

5m.7.21.—Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

© 2021 Lloyd's Register Foundation W1432-0067