Gross Tonnage 5196·81.

of beam at side of uppermost continuous deck. See Sec. 3 (1c) ..... D 30·5 ft.

= 15,419.

Managers W. A. Souter

5c.12.36.

Fees paid

F.E.
(FBD.)

Received by Chief Ship Surveyor ..... Received from Chief Ship Surveyor .....

VESSEL'S NAME Steel Screw M.S."HYLTON" Rpt. Sld. No. 32009

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

1st Long. No. 15419 Depth "d" 24.81

2nd Long. No. 39104 Proportions $= \frac{L}{D}$ 11.42

Framing Channel frames as approved Sheerstrake As approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1'With Freeboard' 'Carrying Vegetable Oil in Deep Tank'

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.

1 Dk. & Shelter Deck.

Cell. DB 354' 1140t, MT 25' 1010t, FPT 230t, APT 240t.

FK, 7 BH (Coll. BH to Shelter Dk. 6 BH to 2nd Dk.), Cem., Lloyd's A &CP

F 34'

27.1.37

© 2020 Lloyd's Register Foundation

W404-0027

" " Angles ..... ✓

Poop Deck, Angle, [or [.....