5c,1,14.

Kingswood now Runney "Hogland".

F.E.

Received by Chief Ship Surveyor 27.1.14 / Received from Chief Ship Surveyor

VESSEL'S NAME Steels "Owen" Rpt. Swc No. 63453

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Transverse No. 79.52 Depth "d" 25.33

Framing: Table No. 3 page 16 Description Bulb Angle as approved

Longitudinal No.

Proportions $\frac{\text{Length}}{\text{Depth}}$ = 10.1

Bridge Deck Sheerstrake as per Rule.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100A-1. (Steel) as recommended.

✠ 100 A-1. (Steel)
1 Dk (pt iron & pt steel)
WB = Cell D.B. a 110' a S & B 42' + 161' 1017 L. FPT 75 L a PT 61 L.
FK. 6 BH. Cem. Lloyds a & cP. P 32' B 110' F 34'

TM 27.1.14

© 2021 Lloyd's Register Foundation

W44-0088

BEAMS, Poop Deck, ~~Angle,~~ Bulb Angle, ~~Plate,~~ ~~Tee Bulb, or Channel~~	6½	3	·40	6½	3	·40
„ Angles on upper edge						