Any modification necessary [Para. 4 (a) to (e)]* C.O.B.

Co-efficient as corrected ..... ·76

If $\frac{6}{10}$ths length covered divide by 2 + 2½

CORRECTION FOR IRON

No. 6610.

Lloyd's Register of Shipping.

LLOYD'S REGISTER, LONDON. REC^D 20 OCT 1923 ANS^D

Ocean Chambers, Lowgate,

Hull, 25th October, 1923

Enclosures

Dear Sir,

I enclose herewith preliminary outline plans for freeboard assignment for Messrs. The Gooleshipbuilding & Repairing Co's No. 257. Two proposals are submitted A and B, and in the B proposal the raised quarter deck is carried through, and the bridge deck is fitted on top. The Builders letter is enclosed, and they ask for the estimated freeboard for both types of vessels.

Forms 11 b. for both proposals are enclosed.

I am, Dear Sir,

Yours faithfully,

Wm. Bazfour

The Secretary,.

London E.C.3.

© 2020 Lloyd's Register Foundation

W472-0174

* If the frames, skin planking, or ceiling are of unusual thickness the breadth of vessel to inside of ceiling should be reported if possible.

† In vessels obtaining an allowance for deck erections under Para. 11 where the sheer drops abaft amidships the height of the R.Q.D. is to be taken from the level of the top of the amidship beam.

‡ State dimensions of freeing port area on back of this for

The Surveyor should state whether the fall in sheer as repo line of keel or to the water line. If measured relatively

© 2020 Lloyd's Register Foundation

Referred to the Chief Ship Surveyor.

26 OCT 1923