F

"PARKHILL"

WRECK BAY
No. 171 Section 2

9826

REPORT OF TOTAL LOSS, CASUALTY, &c.

No. 31334 in R. B. Wreck Book, p. 108/39

Date of writing this report 29th February 1940.

Vessel's Name Steel S.S. "Parkhill" of Methil Tons { Gross 500 / Net 190

Built at Ardrossan When 1915 (YEAR.) 9 (MONTH.) Casualty notice sent to Owner 19/2/40 Owner's reply 21/2/40

Owner's Name Matthew Taylor

Address Methil, Fife.

RETAIN

Case previously before Date
Committee. Last Minute

Particulars of Classification.	
✠ 100A1 2,39	✠LMC
	MS 11,35
S.S. No 3-11,27	BS 12,38
S.S. No 2-35	TSN 12,37 06

Cause of Casualty Overdue.

Particulars of particulars of Casualty This vessel is reported to have left Blyth on the 17th November 1939 for Kirkwall and has not been heard of since.

She was posted missing at Lloyd's on the 3rd January 1940.

The Owners concur.

SOURCE OF INFORMATION.

BRITISH STEAMER PRESUMED LOST

Relatives of the nine members of the crew of the British steamer *Parkhill*, of 500 tons gross, have been notified that the ship must be considered lost with all hands. — LL 26/1

Similar messages have been sent to the relatives of the nine members of the crew of the Parkhill (600 tons), a Methil (Fife) ship, which is also considered to be lost with all hands. — Times 25/1

Suggested Record Missing since 11,39

Date of Committee FRI. 1 MAR 1940

Committee's Minute Missing Since 11,39

5c.6.38. Write Lloyds

RETAIN

© 2020 Lloyd's Register Foundation

W481-0139