5c,1,8.

F.E.

Received by Chief Ship Surveyor *21/8/11*   Received from Chief Ship Surveyor

VESSEL'S NAME *St SS "Benguela"*   Rpt. *Nuv*   No *60884*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake ..	*As approved under new rules*	
Spar Sheerstrake ..	✓	✓

Description of Framing:— *Channel, as approved.*
(viz., ordinary, deep, zed, channel or bulb-angle).

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ *100A·1 ("Steel") as recommended.*

✠ *100A·1 ("Steel")*

2 Dks (Std) & dup framing

WB. 6u 2 Ba 150 u 3+B 46 f 181 1145t FPT 83t APT 25t

FK. 7 BH. 6im. Lloyds A & Co. P 38, B 181 FHH

Date of Build **7.10**

& of Engines 7.10

21/8/11

WS80-0176

"   in Hold   "
WEB-FRAMES, In Fore Body, No. and spacing
"   "   brdth. & thickness
"   No. of Side Stringers   "
WEB-FRAMES, In E. & B. Space, No.& spacing   1   35   9   1   35   9

Tie Plates ....
Deck. Material and thickness *Steel 83 CR*
* If Iron or Steel Deck, state if whole or part, and if Wood

BULKHEADS.